



CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	None
Owner Name:	Site Resource Group Corp		
Address:	PO Box 210 STN Main		
City:	Cold Lake	Province:	AB
Postal Code:	T9M 1P1		
Telephone Number:	(780) 639-4844		
Vehicle Identification Number:	5N6200E1281021387		
Make:	Canadian Hauler	Model:	n/a
Year:	2008	Unit Number:	114-014
Odometer:	KM	Licence Plate Number:	6UY257
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21951
Inspection Technician Name:	Technician Number:
Jasen Reaume	C4695
Inspection Technician Signature:	
Inspection Date:	2026/06/04