010-23

Alberta Government

CV8763107

8008710000876310 7

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:			
GVW:	kg	Brake Type:	Electric		
Owner Name:	SRP PROJECTS LTD				
Address:	151-7620 ELBOW DR SW				
City:	CALGARY	Province:	AB	Postal Code:	T2V1K2
Telephone Number:	(403) 650-6491				
Vehicle Identification Number:	2CPUSM2J2PA055656				
Make:	Cantra	Model:	BT30-24KD		
Year:	2023	Unit Number:	107		
Odometer:	KM	Licence Plate Number:	6NG758	Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
DRB Mechanical Inc.	13000
Inspection Technician Name:	Technician Number:
Jonathan Rullan	B3293
Inspection Technician Signature:	Jonathan Rullan
Inspection Date:	2026/06/09

Version No:1

Alberta Government

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle	Gross Vehicle Weight registered
Trailer	kg

Vehicle Information

VIN	2	C	P	U	S	M	2	J	2	P	A	0	5	5	6	5	6

Unit Number	Year	Make	Model	Odometer
107	2023	Cantra	BT30-24KD	

Registered Owner's Name	Plate Number
SRP PROJECTS LTD	6NG758

Address	Postal Code	Phone Number
151-7620 ELBOW DR SW	T2V1K2	(403) 650-6491

Drum Brakes: A-Full Inspection with Drum Removed Disc Brakes:

	LEFT		FRONT	RIGHT		
110 psi / 10 mm; 110 psi / 10 mm	311.29	mm	Drums/Rotors	311.36	mm	110 psi / 10 mm; 110 psi / 10 mm
	10	mm	Linings/Pads	10	mm	
	NA	mm	Push Rod Travel	NA	mm	
110 psi / 10 mm; 110 psi / 10 mm	311.32	mm	Drums/Rotors	311.34	mm	110 psi / 10 mm; 110 psi / 10 mm
	10	mm	Linings/Pads	10	mm	
	NA	mm	Push Rod Travel	NA	mm	
___ psi / ___ mm; ___ psi / ___ mm		mm	Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
		mm	Linings/Pads		mm	
		mm	Push Rod Travel		mm	
___ psi / ___ mm; ___ psi / ___ mm		mm	Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
		mm	Linings/Pads		mm	
		mm	Push Rod Travel		mm	
___ psi / ___ mm; ___ psi / ___ mm		mm	Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
		mm	Linings/Pads		mm	
		mm	Push Rod Travel		mm	
___ psi / ___ mm; ___ psi / ___ mm		mm	Drums/Rotors		mm	___ psi / ___ mm; ___ psi / ___ mm
		mm	Linings/Pads		mm	
		mm	Push Rod Travel		mm	

Park Brake Lining Left NA mm Right NA mm Trans NA mm

Wheel Torque Checked ☑ Inner NA ft lbs Outer 210 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension			✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment	✓						

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System	✓		
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components	✓		
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance	✓		
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:
BREAK AWAY SYSTEM NOT WORKING. REPAIRED BREAK AWAY SYSTEM.

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage			✓	3A.16. S-Cam Drum Brake System			✓
3A.4. Air Tank			✓	3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls			✓	3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application			✓	3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components			✓	3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber			✓	3A.23. Brake Performance			✓
3A.15. Drum Brake System Components			✓				

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment	✓		
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:
REPAIR REPLACED

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts,& Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:
AXLE 1 PASSENGER SIDE TIRE TREAD AT WEAR BARS. REPLACED TIRES.
AXLE 1 DRIVERS SIDE TIRE TREAD AT WEAR BARS. REPLACED TIRES.
TIRE PRESSURE LOW. ADJUSTED TIRE PRESSURE.
AXLE 1 DRIVERS SIDE HUB CAP PLUG MISSING. REPLACED HUB CAP

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:
SAFETY CHAINS WORN. REPLACED SAFETY CHAINS.
SAFETY CHAIN HOOKS GATE NOT CLOSING. REPLACED SAFETY HOOKS.

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8763107)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/06/03	B3293	13000	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)
2026/06/09

Customer Signature