



CV8677696



80087800008677696

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act****PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	24300 kg	Brake Type:	Air
Owner Name:	1088709 ALBERTA LTD		
Address:	11306 154 ST NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T5M1X7
Telephone Number:	(780) 454-1415		
Vehicle Identification Number:	3ALHCYD20NDMZ5579		
Make:	Freightliner	Model:	Freightliner M2
Year:	2022	Unit Number:	10
Odometer:	226471 KM	Licence Plate Number:	03R105
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Edmonton Diesel Services (1990) Ltd.	15806
Inspection Technician Name:	Technician Number:
Jacob Pou	A5421
Inspection Technician Signature:	
Inspection Date:	2026/10/28