

B01-17



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340548

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: 101056947 SK Ltd. John Warrington Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Inspection Completed Date: 15Jul2026

Inspection Expiry Date: 31Jul2027

Vehicle Details:

VIN: 2LDAH2839DV056335

Hubometer Reading:

Year: 2013

Vehicle Make/Model: LOAD KING/TRAILER

Plate: 928 LNC

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: 101056947 SK Ltd.

John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Vehicle Details:

VIN: 2LDAH2839DV056335

Hubometer Reading:

Year: 2013

Vehicle Make/Model: LOAD KING TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Trailer Hitch (10)	-adjusted fifth wheel
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-changed out 3rd axle left brakepot -fixed abs -changed 2nd axle left slack adjuster, s-cam, and s-cam tube -changed 2nd axle right slack bushing
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	-changed 3rd axle both hub caps -changed 1st axle right hubcap -changed 2nd axle left wheel seal -changed 2nd axle left hub cap
		x		Tires/Wheels (9)	-changed out all 3rd axle tires
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	-changed out 3rd axle both shocks -changed out 2nd axle lift air bag on left side -fixed air leak on 2nd axle right leveling valve -changed 2nd axle both shocks -changed 1st axle both shocks
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 3 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 35.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 38.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 3 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 58.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 16 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 43.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 16 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 38.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 16 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A340548	Inspection Completed Date: 15Jul2026
----------------------------------	-----------------	--------------------------------------