INSPECTION CERTIFICATE Manitoba B02-5

Manitoba C078483

Date Inspection Started	16	03	26
	DAY	MO.	YR.
Date Inspection Completed	18	03	26
Date Inspection Expiry	31	03	27

Station Number: 75135 — Station Name / City: Wehrma Ltd 2007 Ltd.

Mechanic Number: 117741 — Mechanic Signature — Station Phone Number: 204 325 4966.

Vehicle Owner: Elskamp Farms Inc.
Address: Rd 82N Woodlands MB R0C 1T0 — City, Province, Postal Code, Phone

- [x] Pass/Safe Vehicle
- [x] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: TL2628 Prov.: MB NSC # Odometer Reading Odom. Type km ml

Vehicle Identification Number: 1TDH430284B105207 Make: Timpte Model: Hopper Year: 2004 Unit #

[x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bu

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Sectior

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type: 16-C Axle 2 Slack Clevis Pins Siezed; 16-A Axle 1&2 LF, RR Scam bushings; 15-F Axle 2 Left Wheel Seal fail.
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) 7-A Side Rail Corrosion at Rear.
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 2-B Axle 2 Rite Outside Tire fail.
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E *Circle appropriate Letter for Internal Brake Component Inspection*

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	3/4	3/4	16.54	16.53	1½	1½
2	11/16	9/16	16.52	16.54	1½	1½
3						
4						
5						
Final Measurement						

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	7	8	8	8					100	100	100	100				
2	8	7	4	X				12	100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: ____________ Signature **Date:** ____________

Ce document peut être obtenu en français sur demande