

03936582

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

B02-8

Vehicle Standards and Inspect
Box 45064 Regent Postal Ok
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A901914

Date Inspection Started **01** **04** **25**
DAY MO. YR.

Date Inspection Completed **01** **04** **25**
DAY MO. YR.

Inspection Expiry Date **30** **04** **26**
DAY MO. YR.

Station Number **A100184** Station Name **PBX Truck Service**
City **Winnipeg**

Mechanic Number **M05131** Mechanic Signature **[Signature]**
Station Phone Number **204-326-3155**

Vehicle Owner **Terrain Transport**
Address **P/0 BOX 1068 STE ANNE MB R5H 1C1**
City **Ste Anne** Province **MB** Postal Code **R5H 1C1** Phone

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number **T142892** Prov. **MB** NSC # **1** Odometer Reading **1** Odom. Type **km**

Vehicle Identification Number **1J3V1532B4JL0511144** Make **Wabash** Model **53' Reeler** Year **2017** Unit # **R-127**

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck **GVWR** KGS **Truck Tractor** **Trailer** **Semi-Trailer** **Bus** **School Bus** **Coach Bus**

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																															
X		Section 1 - Power Train: Defects (if any)																																																															
X		Section 2 Suspension: Defects (if any) 25° LF Airbag Levelling valve bolt loose																																																															
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 216: All Clevis pins are worn 215: LR+RF brake drums worn RF Brake shoes worn. 23: Service gear hand separated.																																																															
X		Section 4 - Steering: Defects (if any)																																																															
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																															
X		Section 6 - Lamps: Defects (if any) 51: Left midship turn signal mounted backwards. signals shorting out																																																															
X		Section 7 - Electrical System: Defects (if any)																																																															
X		Section 8 - Body: Defects (if any) 210: Rear bumper requires welding																																																															
X		Section 9 - Tire & Wheel: Defects (if any)																																																															
<table border="1"> <thead> <tr> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th rowspan="2">Axe</th> <th colspan="2">Initial</th> <th>Corrected</th> <th colspan="2">Initial</th> <th>Corrected</th> <th></th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th></th> </tr> </thead> <tbody> <tr> <td>1</td> <td>14</td> <td>14</td> <td>14</td> <td>14</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>14</td> <td>14</td> <td>16</td> <td>16</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			Tread Depth				Air Pressure				Axe	Initial		Corrected	Initial		Corrected		L	R	L	R	L	R		1	14	14	14	14	100	100	100	2	14	14	16	16	100	100	100	3								4								5							
Tread Depth				Air Pressure																																																													
Axe	Initial		Corrected	Initial		Corrected																																																											
	L	R	L	R	L	R																																																											
1	14	14	14	14	100	100	100																																																										
2	14	14	16	16	100	100	100																																																										
3																																																																	
4																																																																	
5																																																																	
Section 10 - Coupling Devices: Defects (if any)																																																																	

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: **Advise: LR Airbag / Both rear wheel seals leaking.**

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: **Signature** Date: