

03939737

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba B03-1

Vehicle Standards and Insp
Box 45064 Regent Postal Outl
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba DECAL

A975255

Date Inspection Started: DAY 21, MO. 11, YR. 2015
 Date Inspection Completed: DAY 21, MO. 11, YR. 2015
 Inspection Expiry Date: DAY 30, MO. 11, YR. 2016

Station Number: C1015619 Station Name: *Champion Power Unit* City: _____
 Mechanic Number: M14121414 Mechanic Signature: _____ Station Phone Number: 204 219 2222
 Vehicle Owner: 2421251 *Manitoba LTD*
 Address: *Ray 528 ST ADAM* City: _____ Province: MB Postal Code: R5A 1A0 Phone: _____

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
 Licence Number: FM12512 Prov. MB NSC # _____ Odometer Reading: 41848 Odom. Type: km mi
 Vehicle Identification Number: 2J79K7EWSK1K1T0111089 Make: *ITS* Model: *Ray* Year: 2019 Unit #: 2863
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																										
X		Section 1 - Power Train: Defects (if any)																																																																																										
X		Section 2 Suspension: Defects (if any)																																																																																										
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																																																										
		Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7/8</td> <td>7/8</td> <td>16.508</td> <td>16.502</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>7/8</td> <td>7/8</td> <td>16.500</td> <td>16.505</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>3</td> <td>7/8</td> <td>7/8</td> <td>16.502</td> <td>16.501</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/8	7/8	16.508	16.502	1 1/2	1 1/2	2	7/8	7/8	16.500	16.505	1 1/2	1 1/2	3	7/8	7/8	16.502	16.501	1 1/2	1 1/2	4							5																																																
Axle	Lining			Drum/Rotor		Stroke																																																																																						
	L	R	L	R	L	R																																																																																						
1	7/8	7/8	16.508	16.502	1 1/2	1 1/2																																																																																						
2	7/8	7/8	16.500	16.505	1 1/2	1 1/2																																																																																						
3	7/8	7/8	16.502	16.501	1 1/2	1 1/2																																																																																						
4																																																																																												
5																																																																																												
X		Section 4 - Steering: Defects (if any)																																																																																										
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																										
X	X	Section 6 - Lamps: Defects (if any) <i>1H Side Marker Lamp (out)</i> <i>1H license plate lamp</i>																																																																																										
X		Section 7 - Electrical System: Defects (if any)																																																																																										
X		Section 8 - Body: Defects (if any)																																																																																										
X	X	Section 9 - Tire & Wheel: Defects (if any) <i>ALL INFLATION PRESSURE</i>																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>24/32</td> <td>24/32</td> <td>21/32</td> <td>21/32</td> <td>90</td> <td>90</td> <td>92</td> <td>90</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>21/32</td> <td>21/32</td> <td>21/32</td> <td>21/32</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>27/32</td> <td>27/32</td> <td>27/32</td> <td>27/32</td> <td>90</td> <td>90</td> <td>95</td> <td>90</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	24/32	24/32	21/32	21/32	90	90	92	90	100	100	100	100	2	21/32	21/32	21/32	21/32	90	90	90	90	100	100	100	100	3	27/32	27/32	27/32	27/32	90	90	95	90	100	100	100	100	4													5												
Axle	Tread Depth				Air Pressure																																																																																							
	Initial			Corrected		Initial		Corrected																																																																																				
	L	R	L	R	L	R	L	R																																																																																				
1	24/32	24/32	21/32	21/32	90	90	92	90	100	100	100	100																																																																																
2	21/32	21/32	21/32	21/32	90	90	90	90	100	100	100	100																																																																																
3	27/32	27/32	27/32	27/32	90	90	95	90	100	100	100	100																																																																																
4																																																																																												
5																																																																																												
X		Section 10 - Coupling Devices: Defects (if any)																																																																																										

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: _____ Signature _____ Date: _____