



Commercial Vehicle Inspection Report

Decal Number: GP96550
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21915876

Inspection Result:

PASS

FACILITY: Steve's Inspections / S20014
INSPECTOR: COLLIER, STEPHEN / 203108
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Sep-11 01:43 PM PDT
INSP. COMPLETE: 2026-Sep-11 02:43 PM PDT

B03-3

VEHICLE JUR: British Columbia
PLATE #: 2D1G6G
LICENCED GVW(kg): 12500
VEHICLE YEAR: 2003
MAKE: KENWORTH
MODEL:

REGI: 01211013
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 325671 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1XKDD89X13R969294
OWNER/LESSEE NAME: BRADS TRUCKING LTD.,
ADDRESS: 4301 PIDHERNY RD
Prince George, British Columbia
V2K 4Z4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPAIRED FUEL LEAK AT REAR OF TRANSMISSION
Section 2 - Suspension	Repaired (same day) REPLACED WEATHERED AIR BAGS
Section 3 - Brake System	Repaired (same day) REPLACED #3 AXLE BRAKE CHAMBERS
Section 3A - Air Brakes	Repaired (same day) REPLACED DAMAGED AIR LINE RH #3
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)		Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	33	33	8		18	18	18	18	✓
2	Clamp	30	Automatic	34	34	18		18	18	18	18	
3	Clamp	30	Automatic	34	34	18		18	18	18	18	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	35	45
3	75	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	17	18
Lining (Shoe)	12	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Sep-11 02:43 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CV/SEP014

9/11/2026 2:43:58 PM PDT