



Commercial Vehicle Inspection Report

Decal Number: GN03950
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21810053

B03-8
Inspection Result:
PASS

FACILITY: CULLEN DIESEL POWER LTD. / S5918
INSPECTOR: Wetherup, David James / 200077
WORK ORDER #: R160007045
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Jun-11 03:13 PM PDT
INSP. COMPLETE: 2026-Jun-12 09:13 AM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 0
VEHICLE YEAR: 2019
MAKE: RENN
MODEL: SL170
REGI: 13049731
UNIT/FLEET#:
BODY STYLE: Pup Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2SFNE3693K1046237
OWNER/LESSEE NAME: AIM ROADS INC., AIM ROADS INC.
ADDRESS: 1160 HWY 97A, 1160 HWY 97A
Armstrong, British Columbia
V0E1B6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) #2 LHS SHOCK REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) BOX UP INSTALLED.
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	25.4	25.4
2	Clamp	30	Automatic	25.4	25.4
3	Clamp	30	Automatic	31.8	31.8

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8	7	6	9	
15	16	15	16	
12	11	14	14	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	58	60
2	55	65
3	45	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	14
Lining (Shoe)	15	14
Lining (Shoe)	16	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Wetherup, David James
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jun-12 09:13 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/12/2026 9:13:43 AM PDT