04045679 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba B04-3

Vehicle Standards and Inspections
Box 45064 Regent Postal Ou
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C080630

Date Inspection Started	08 DAY	05 MO.	26 YR.
Date Inspection Completed	08 DAY	05 MO.	26 YR.
Inspection Expiry Date	31 DAY	05 MO.	27 YR.

Station Number: A16473 — T4 TRANSPORT LTD (Station Name) — City

Mechanic Number: M10725 — Mechanic Signature — 204-856-5531 (Station Phone Number)

Vehicle Owner: PORTAGE TRANSPORT INC

Address — City — Province — Postal Code — Phone

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: T69702 — Prov.: MB — NSC #: — Odometer Reading: — Odom. Type: ☐ km ☐ mi

Vehicle Identification Number: 1UYVS25B3BU111047 — Make: UTILITY — Model: REEFER — Year: 2011 — Unit #: 53145

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck (GVWR ____ KGS) ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
X	X	**Section 2 Suspension:** Defects (if any) 3 SHOCKS LEAKING 2.7.c
X		**Section 3 - Brake Systems:** 3H (3A) — Defects (if any) — Circle Brake Type
		Section 4 - Steering: Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

COPIED SCANNED

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	11/16	10/16	16.545	16.546	1½"	1½"
2	10/16	10/16	16.552	16.566	1"	1"
3						
4						
5						
	Final Measurement					

Axle	Tread Depth mm Initial L		Initial R		Corrected L		Corrected R		Air Pressure psi Initial L	Initial R		Corrected L		Corrected R	
1	8	8	8	8					90	90	95	95	100	100	100	100
2	8	8	8	8					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE