Vehicle History Report #: 63256390 Report Date: July 30, 2025 | 6:37 p.m. EDT Report Status: Complete Reference:

2017 CHEVROLET SILVERADO K2500 HEAVY DUTY LTZ

Pickup | 8 Cylinders | Flexible 1GC1KWEG6HF195439

Country of Assembly: United States Last Reported Odometer: 399,999 KM





Last Registered In: Manitoba (Normal)



11 Service Records Found







Not Actively Declared Stolen



No Import/Export Records Found


Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 30, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
9 2017 Sep 21	Russell, Manitoba, Canada	
	Estimate: Left Front Estimate Date: n/a	\$4,289.80
	Claim: Collision Left Front	Not Reported
① 2017 Oct 3	Russell, Manitoba, Canada	
	Estimate: Left Front Estimate Date: n/a	\$2,608.49
	Claim: Collision Left Front	Not Reported
① 2018 Oct 27	Russell, Manitoba, Canada	
	Estimate: Left Front Estimate Date: n/a	\$5,250.69
	Claim: Collision Left Front	Not Reported
2021 Jun 17	Brandon, Manitoba, Canada	
	Estimate: Front Center Estimate Date: 2021 Jun 23	\$14,636.37
	Claim: Collision Front	Not Reported



Registration

This vehicle has been registered in the province of Manitoba in Canada with Normal branding.


We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2017 May 10		Paragon Sales Ltd.	Vehicle serviced	
		Langenburg, Saskatchewan, Canada	Pre-delivery inspection completed	
2017 Jun 19 11,156 KM		Murray Chevrolet Inc	Vehicle serviced	
		Winnipeg, Manitoba, Canada	Maintenance inspection completed	
		1 3	Antifreeze/coolant checked	
			 Fluids checked 	
			Oil and filter changed	
			 Tire condition and pressure checked 	
			Tire pressure monitoring system reset	
			Vehicle washed/detailed	

	ODOMETER	SOURCE	DETAILS
2017 Oct 22	53,388 KM	Great Canadian Oil Change Brandon, Manitoba, Canada	Vehicle serviced • Fluids checked • Oil and filter changed
2017 Dec 15	70,399 KM	Great Canadian Oil Change Brandon, Manitoba, Canada	Vehicle serviced Fluids checked Oil and filter changed
2018 Jan 23	80,916 KM	Paragon Sales Ltd. Langenburg, Saskatchewan, Canada	Vehicle serviced • Mass air flow sensor replaced
2018 Apr 12	103,291 KM	Paragon Sales Ltd. Langenburg, Saskatchewan, Canada	Vehicle serviced • Axle seal(s) replaced
2021 Jun 30		Murray Chevrolet GMC Brandon Brandon, Manitoba, Canada	Vehicle serviced Maintenance inspection completed Sensing and diagnostic module replaced
2021 Jul 6	399,999 KM	NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Vehicle serviced • Alignment checked • Four tires balanced • Tire(s) balanced • Tire(s) mounted
2022 Mar 7		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Vehicle serviced • Alignment checked
2023 Mar 30		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Vehicle serviced Engine/powertrain computer/module reprogrammed Transmission computer/module reprogrammed
2023 Aug 3		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Vehicle serviced • Alignment checked



Recall #: N192220470 | Power Sliding Rear Window Defroster Failures (Canada Only) Recall Date: 2019 Jun 27

Recall Description

General Motors has approved a safety recall in Canada for certain 2014-2019 model year Chevrolet Silverado and GMC Sierra vehicles equipped with a power sliding rear window (RPO A48). In some of these vehicles, areas of high electric resistance on the rear defroster circuit, caused, in part, by mechanical stress from opening and closing the rear power window, intrusion of debris, and use of the rear defroster may, over time, generate heat which could melt the areas surrounding the circuit. In rare instances, this heat could cause a non-propagating fire, increasing the risk of property damage or injury.

Remedy

Dealers will replace the buss bar covers and the contact cover, and for certain vehicles, will reprogram the HVAC calibration to disable the rear defroster from automatically turning on at keyed start. Please note that the rear defroster will automatically turn on during remote start or by pushing the manual button and is not affected by this calibration. If the rear window or sliding glass assembly appears damaged due to an occurrence of high electrical resistance on the rear defroster circuit, they will also be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit **GM's website**. (https://my.gm.ca/gm/en/recalls)



This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 May 10		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as white
2017 May 10		Paragon Sales Ltd. Langenburg, Saskatchewan, Canada	Service Record	Vehicle serviced
2017 Jun 19	11,156 KM	Murray Chevrolet Inc Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Sep 21		Insurance Records Russell, Manitoba, Canada	Collision	Estimate Date: n/a Left Front
2017 Sep 21	50,026 KM	Russell, Manitoba, Canada	Collision	Left Front
2017 Oct 3		Russell, Manitoba, Canada	Collision	Left Front
2017 Oct 3		Insurance Records Russell, Manitoba, Canada	Collision	Estimate Date: n/a Left Front
2017 Oct 22	53,388 KM	Great Canadian Oil Change Brandon, Manitoba, Canada	Service Record	Vehicle serviced
2017 Dec 15	70,399 KM	Great Canadian Oil Change Brandon, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jan 23	80,916 KM	Paragon Sales Ltd. Langenburg, Saskatchewan, Canada	Service Record	Vehicle serviced
2018 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2018 Apr 12	103,291 KM	Paragon Sales Ltd. Langenburg, Saskatchewan, Canada	Service Record	Vehicle serviced
2018 Oct 27		Insurance Records Russell, Manitoba, Canada	Collision	Estimate Date: n/a Left Front
2018 Oct 27	169,140 KM	Russell, Manitoba, Canada	Collision	Left Front

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2019 Jun 27		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192220470
2020 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2021 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2021 Jun 17		Russell, Manitoba, Canada	Collision	Front
2021 Jun 23	427,481 KM	Insurance Records Brandon, Manitoba, Canada	Estimate Repair	Incident Date: 2021-06-17 Front Center
2021 Jun 30		Murray Chevrolet GMC Brandon Brandon, Manitoba, Canada	Service Record	Vehicle serviced
2021 Jul 6	399,999 KM	NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Service Record	Vehicle serviced
2022 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2022 Mar 7		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Service Record	Vehicle serviced
2023 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2023 Mar 30		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Service Record	Vehicle serviced
2023 Aug 3		NAPA AutoCare Thunder Creek Auto Russell, Manitoba, Canada	Service Record	Vehicle serviced
2024 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2024 Jun 18		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2025 Mar 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Manitoba, Canada		Previous Use: Commercial
				Vehicle colour noted as white
2025 Jul 4		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Manitoba, Canada		Previous Use: Commercial
				Vehicle colour noted as white



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. See this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.

