

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2020 Kenworth W9 Series****Test Information**

Engine	Cummins ISX / X15 (15.0)
Engine Serial	CMMNS*6X3u17D1500000000*80129781*0000000000
VIN	1XKWD40XXLJ960402
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: CBE (Cab Behind Engi
Test Time	Oct. 15, 2025, 1:29 p.m.
File Length	44.852 s

Usage

Label	Value	Units
Engine Odometer	428,601	mi
Engine Total Hours of Operation	10,769.75	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	0	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Engine #1	Engine Oil Pressure	Low-moderate severity	48
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater	High-moderate severity	1
Previous	Engine #1	Fuel Level 1	Abnormal Update Rate	1
Previous	Engine #1	Engine Variable Geometry Turbocharger Actuator Software Identification	Abnormal Update Rate	3
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	3
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater	High-moderate severity	1