

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date:

Inspection Number:

GK31401 2026-Jan-31 21422226

Inspection Result:

ACILITY: NSPECTOR: JUST DIESEL / \$7036

INSP. TYPE:

Complete

INSP. START:

2025-Jun-17 10:00 AM PDT

NORK ORDER #:

ÆHICLE JUR:

KIPLING, DIONE / 300529

INSP. CLASS:

Class 2 - Heavy Vehicle with LGVW

INSP. COMPLETE:

2025-Jul-11 08:00 AM PDT

INSP. REASON:

5501 kg or more

Semi-annual 12476092

06

VIN:

5KKRALCK67PY55711

LATE #:

MC3874

British Columbia

UNIT/FLEET#:

OWNER/LESSEE NAME:

THARROW CRANE LTD., THARROW

CRANE LTD.

JCENCED GVW(kg): 56100

2007

BODY STYLE: ODOMETER:

Truck Tractor 617429 KM

ADDRESS:

PO BOX 1501 STN A, PO BOX 1501

Prince George, British Columbia

V2L 4V5, Canada

/EHICLE YEAR: MAKE:

IODEL:

WESTERN ST

HUB ODOMETER:

BRAKE TYPE:

FUEL TYPE:

Air Diesel

Vehicle Identification (VIN) Section 1 - Power Train

Passed

Passed

Section 2 - Suspension

Passed with Caution

REPLACE L2 SPRING BUSHING, TIGHTEN SUSPENSION BOLTS AS NEEDED, DRIVE AXLE

BUSHINGS STARTING TO SHOW SIGNS OF WEAR

Section 3 - Brake System Section 3A - Air Brakes

Repaired (same day) Repaired (same day) SHIM L3 SLACK ADJUSTER, SECURE BRAKE LINES AS NEEDED

Section 3H - Hydraulic Brakes

Not Applicable

REPAIR AIR LEAK UNDER CAB AREA

Section 4 - Steering

Repaired (same day)

TIGHTEN STEER SHAFT YOKE BOLT

Section 5 - Instruments and Auxiliary

Equipment

Not Applicable

Section 6 - Lamps

Passed Passed

Section 7 - Electrical System Section 8 - Frame and Bady

Passed

Section 9A - Tires

Passed

Repaired (same day)

REPLACE PASSENGER STEER HUB CAP, REPLACE L3 RIM

Section 9B - Wheels Section 10 - Coupling Devices

Passed

Section 11 - Other Vehicle Components

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	32	14			14	✓
2	Clamp	30	Automatic	38	38	20	20	22	22	
3	Clamp	30	Automatic	38	38	19	19	7	7	
4	Clamp	30	Automatic	38	38	20	20	8	7	
Comment:						Comment:				



Commerciai venicie Inspection Report

Deser Humber. Decal Expiry Date:

Inspection Number:

ころうしゃらい

2026-Jan-31 21422226

PASS

Air Brake Camebat	ft Rotation (dear	eec)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Air Brake Camshaft Rotation (degrees) Axles Left Right		,	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	40	42	Lining (Shoe)	17	17	Drum	2011	gii.	
2	44	39	Lining (Shoe)	17	17	Drum			
3	55	43	Lining (Shoe)	16	17	Drum			
4	65	32	Lining (Shoe)	16	18	Drum -			
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.			

nspection Comments:

las this Vehicle been road tested?

No

Road Test Date: 🗼

Road Tester:

nspector:

KIPLING, DIONE

Signature:

his Inspection Report was submitted to CVSE on 2025-Jul-11 09:57 AM PDT

he Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.