



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD86178
Decal Expiry Date: 2025-Mar-31
Inspection Number: 21084644

Inspection Result:

PASS

FACILITY: JUST DIESEL / S7036
INSPECTOR: KIPLING, DIONE / 300529
WORK ORDER #:
INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW
INSR. REASON: Semi-annual
INSR. START: 2024-Sep-18 10:00 AM PDT
INSR. COMPLETE: 2024-Sep-25 10:00 AM PDT

VEHICLE JUR: British Columbia
PLATE #: SA3580
LICENCED GVW(kg): 56000
VEHICLE YEAR: 2009
MAKE: KENWORTH
MODEL:
REGI: 13971730
UNIT/FLEET#: WT-01
BODY STYLE: Truck Tractor
VIN: 1XKDD40X49R941889
OWNER/LESSEE NAME: THARROW CRANE LTD.,
ADDRESS: PO BOX 1501 STN A, PO BOX 1501
STN A
Prince George, British Columbia
V2L 4V5, Canada
ODOMETER: 519754 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPAIR EXHAUST LEAK
Section 2 - Suspension	Repaired (same day) REPLACE L2, L3 SHOCK
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACE DRIVER SIDE DRAG LINK
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACE DRIVERS SIDE WINDSHIELD
Section 9A - Tires	Passed with Caution STEER TIRES ON ORDER
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	32	11			12	✓
2	Clamp	30	Automatic	38	38	19	19	19	19	
3	Clamp	30	Automatic	38	38	6	7	7	8	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	52	Lining (Shoe)	17	17	Drum		
2	65	61	Lining (Shoe)	16	16	Drum		
3	40	43	Lining (Shoe)	18	18	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: KIPLING, DIONE

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Sep-25 12:51 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

2/SE0014

12/25/2024 12:51:25 PM PDT