



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GK07850
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21422488

Inspection Result:

PASS

FACILITY: JUST DIESEL / S7036 **INSP. TYPE:** Complete **INSP. START:** 2025-Jul-10 01:30 PM PDT
INSPECTOR: FREIMULLER, CURTIS E WALTE / 114809 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2025-Jul-11 11:00 AM PDT
WORK ORDER #:

VEHICLE JUR: British Columbia **REGI:** 11091288 **VIN:** 2LDPF4035E9057712
PLATE #: 34752J **UNIT/FLEET#:** PH401 **OWNER/LESSEE NAME:** THARROW CRANE LTD.,
PERMITTED GVW(kg): 999999 **BODY STYLE:** Flat Deck Trailer **ADDRESS:** PO BOX 1501 STN A,
VEHICLE YEAR: 2014 **ODOMETER:** Prince George, British Columbia
MAKE: LODE KING **HUB ODOMETER:** V2L 4V5, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Not Applicable
Section 5 - Instruments and Auxiliary Equipment Not Applicable
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	38	14	14	14	14	
2	Clamp	30	Automatic	38	38	13	13	12	12	
3	Clamp	30	Automatic	38	38	10	10	10	8	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	62	64	Lining (Shoe)	17	13	Drum		
2	32	60	Lining (Shoe)	19	13	Drum		
3	70	72	Lining (Shoe)	14	12	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: FREIMULLER, CURTIS E WALTE

Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-11 11:40 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

No personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

2/SED014

7/11/2025 11:41:13 AM PDT