



Commercial Vehicle Inspection Report

Decal Number: GH36221
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21199967

Inspection Result:
PASS

FACILITY:	JUST DIESEL / S7038	INSP. TYPE:	Complete	INSP. START:	2024-Dec-23 08:00 AM PST
INSPECTOR:	FREIMULLER, CURTIS E WALTER / 114908	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Dec-31 11:15 AM PST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	10524236	VIN:	3C7WDNBL3CG228457
PLATE #:	MM0575	UNIT/FLEET#:	07	OWNER/LESSEE NAME:	THARROW CRANE LTD.,
REGISTERED GVW(kg):	12000	BODY STYLE:	Dump Truck	ADDRESS:	PO BOX 1501 STN A, PO BOX 1501 STN A
VEHICLE YEAR:	2012	ODOMETER:	264246 KM		Prince George, British Columbia
MAKE:	DODGE/RAM	HUB ODOMETER:			V2L 4V5, Canada
MODEL:		BRAKE TYPE:	Hydraulic		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed with Caution	OIL LEAKS SWEATING, REPAIR CHECK ENGINE LIGHT AND ABS
Section 2 - Suspension	Repaired (same day)	TIGHTEN FRONT SHOCK BOLTS
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPLACE REFLECTIVE TAPE
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	13			12	✓	Pad	15	15	Rotor	38.82	38.68
2	10	9	9	10		Pad	14	14	Rotor	39.24	38.41
Comment:						Comment:			Comment:		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: FREIMULLER, CURTIS E WALTER Signature: _____

This Inspection Report was submitted to CVSE on 2025-Jan-09 11:20 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.