B11-1 WOV

Commercial Vehicle Inspection Report

Decal Number: PA16575
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21898488

Inspection Result: **PASS**

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	**INSP. TYPE:**	Re-inspection	**INSP. START:**	2026-Aug-27 02:00 PM MST
INSPECTOR:	PEREGOODOFF, DAVID JAMES / 112485	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Aug-27 02:30 PM MST
WORK ORDER #:		**INSP. REASON:**	Semi-annual		
ORIGINAL INSP. #:	21888616				

B11-1

VEHICLE JUR:	British Columbia	**REGI:**	10984511	**VIN:**	1FVHC5DE47HX42317
PLATE #:	WX3026	**UNIT/FLEET#:**	S01	**OWNER/LESSEE NAME:**	TALL TEN, RESOURCES LTD
LICENCED GVW(kg):	26500	**BODY STYLE:**	Van	**ADDRESS:**	14110 256 RD
VEHICLE YEAR:	2007	**ODOMETER:**	423182 KM		Montney, British Columbia
MAKE:	FREIGHTLIN	**HUB ODOMETER:**			V1J 8L1, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	#1 U JOINT MISSING BOLT
Section 2 - Suspension	Passed	
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Passed	AIR LEAK @ COMPRESSOR, UNDER CAB, DASH, #1L BRAKE AND DRUM
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	WINDSHIELD, X MEMBER BEFORE #2 BROKEN, FRONT R BOX MOUNT LOOSE
Section 9A - Tires	Passed	#3 AXLE TIRES
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30	Automatic	40	42
3	Clamp	30	Automatic	40	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7			8	✔
18	18	20	14	
10	15	6	11	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	115	85
2	0	0
3	32	30

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	10	14
Lining (Shoe)	10	10
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	420.42	420.39
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: PEREGOODOFF, DAVID JAMES **Signature:**

This Inspection Report was submitted to CVSE on 2026-Aug-27 05:16 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/27/2026 5:20:07 PM MST