



Commercial Vehicle Inspection Report

Decal Number: **GM05260**
Decal Expiry Date: **2027-May-31**
Inspection Number: **21794052**

Inspection Result:
PASS

FACILITY: SEMI TECH LUBE & REPAIR LTD. / S17551
INSPECTOR: GILL, JAGDEEP SINGH / 301479
WORK ORDER #: WF6
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2026-May-29 05:00 PM PDT
INSP. COMPLETE: 2026-May-29 10:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 09457K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2018
MAKE: TYCROP
MODEL:
REGI: 12515855
UNIT/FLEET#: WF6
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2T9YAAZCXJD016501
OWNER/LESSEE NAME: DOUBLE TREE, HOLDINGS LTD.
ADDRESS: 1730 FOY ST
Abbotsford, British Columbia
V2T 6B1, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) #2 & #3 SHOCK ABSORBERS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MULTIPLE MARKER LAMPS; LICENSE PLATE LAMP
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34.9	34.9
2	Clamp	30	Automatic	34.9	34.9
3	Clamp	30	Automatic	34.9	34.9

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7	7	6	6	
8	8	7	9	
7	7	6	6	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	62
2	58	56
3	63	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	16	16
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: GILL, JAGDEEP SINGH

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jun-01 06:30 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/1/2026 6:30:12 AM PDT