

432 Corduroy Road 191 Dalton Ave P:(613)443-5369 F:(613)443-5340

KINGSTON P:(613)544-1212 F:(613)544-4080

PETERBOROUGH 1874 Technology Dr. Vars, ON KOA 3H0 Kingston, ON K7K 6C2 Peterborough, ON K9J 6X7 Thunder Bay, ON P7K 0V3 Belleville, ON K8N 4Z5 P:(705)742-4747 F:(705)742-4848

THUNDER BAY 2730 W. Arthur St P:(807)939-2424 F:(807)939-1955

BELLEVILLE - TRP 1037B Wallbridge-Loyalist Rd. P:(613) 967-1212 F:(613) 967-1214

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE Work Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD VARS, ON KOA 3H0

Ship To:

R&B TRUCKING INC. 4780 FRANK KENNY ROAD VARS, ON K0A 3H0



613 229-3857

					Tax ID Date:	Tax ID: Page	e 1 of 7
YEAR	1	MAKE / MODEL	VIN		LICENSE	MILEAGE	AUTH
2012	Ker	nworth / T170	2XKHDN9X6CM9	956275	PA51432	325111K	#
DEL DATE	OPI	EN DATE / TIME	ENGINE MODEL /	SERIAL #	P.O. NUMBER	COMPLETE	UNIT/STOCK
01-16-12	03-	05-24/07:10AM	PX-8 / 7330	3134	#	05-31-24	KW-12
DEL MILEAGE		MEMO		-	TRANSMISSION M	SERVICE WRITER	
				E	FULLER FRO112	10C 10-SPEED	GSL*GSL
					CONCEPT 2 /	′ К0868821	
ENGINE	HOURS	7761.0	REEFER HOURS	0.	0 :	STBY HOURS	0.0

1 DIAG CAUSE OF PASSENGER SIDE BRAKE LIGHT INOP - REPAIR BRAKE LIGHT CAUSE:

CORROSION, BROKEN WIRING.

CORRECTION:

- BROUGHT UNIT IN.
- CONFIRMED BRAKE LIGHT NOT OPERATIONAL.
- REMOVED LIGHT TO INSPECT WIRING, FOUND BROKEN WIRING AND CORROSION AT CONNECTOR.
- REPLACED CORRODED CONNECTOR, REPAIRED BROKEN WIRING.
- LIGHT NOW OPERATING AS INTENDED, REINSTALLED IN UNIT.
- REPAIR COMPLETE.

TOTAL LABOR TOTAL PARTS

169.20 1.86

List Qty Part Number Description Unit Extended _____ 1 67050GRC PIGTAIL, 2.33 1.86 1.86

3 REPLACE LOWER RAD HOSE

CAUSE:

LOWER HOSE DETERIORATING.

CORRECTION:

- DRAIN COOLANT.
- REMOVED LOWER RAD HOSE AND CLAMPS.
- INSTALL NEW HOSE AND CLAMPS.
- FILL COOLANT AND CLEAR AIR GAPS.
- PRESSURE TESTED SUCCESSFULLY, NO LEAKS.
- REPAIR COMPLETE.

TOTAL LABOR TOTAL PARTS

338.40

62.84

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

I agree and acknowledge that if I fail to pay, in whole or in part, any invoices that are due and owing for the repairs to this vehicle, that in addition to any statutory remedies available to it, Kenworth Ontario has the right to take repossession of the above vehicle and hold it or to sell it and recover all monies owed. I agree that Kenworth Ontario shall be entitled to compensation for any fees it incurs in the repossession, storage and sale of the above

I understand that all warranty claims are subject to change based on the manufacturer's discretion. I assume full responsibility for all necessary repair expenses upon c	aim rejection.
---	----------------

CUSTOMER: X	DATE:



OTTAWA 432 Corduroy Road

Vars, ON K0A 3H0 P:(613)443-5369 F:(613)443-5340

KINGSTON

191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080

PETERBOROUGH

810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848 **THUNDER BAY** 2730 W. Arthur St Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



					Та	x ID Date: Ta	x ID: Page	20	ot 7
YEAR		MAKE / MODEL	VIN	Ī		LICENSE	MILEAGE		AUTH
2012	K	enworth / T170	2XKHDN9X60	CM95627	5	PA51432	325111K		#
DEL DATE	C	PEN DATE / TIME	ENGINE MODEL	/ SERIA	L#	P.O. NUMBER	COMPLETE		UNIT/STOCK
01-16-12	0.3	3-05-24/07:10AM	PX-8 / 73	PX-8 / 73303134		#	05-31-24		KW-12
DEL MILEAGE		MEMO		TRA			L/SERIAL #	SI	ERVICE WRITER
					FULI	LER FRO112100	: 10-SPEED		GSL*GSL
					CONCEPT 2 / K0868821				
ENGINE HO	OURS	7761.0	REEFER HOURS		0.0	STB	Y HOURS		0.0

Qty	Part Number	Description	List	Unit Ex	tended
2	24108MSC	NO. 4 WOR	0.88	0.44	0.88
2	CT9436TRP	CLAMP-CON	21.28	10.64	21.28
1	D1030-2585	HOSE-RADI	61.16	40.68	40.68

8 CUSTOMER REPORTS WABASTO SYSTEM INOP. DIAG AND REPORT. CAUSE:

UNIT REQUIRED GENERAL TEAR DOWN AND CLEANING OF FLAME SENSOR.

CORRECTION:

- TESTED FOR POWER AT INLINE PUMP, NONE FOUND.
- FOLLOW WIRE TO BURNER AND TESTED CONTINUITY, TESTED OKAY.
- REMOVE MODULE FROM UNIT, TEAR DOWN AND CLEAN FLAME SENSOR.
- REASSEMBLE, INSTALL AND TEST, UNIT NOW IN GOOD OPERATION.
- REPAIR COMPLETE.

TOTAL LABOR

1,203.20

9 PERFORM OIL CHANGE SERVICE - FUEL FILTERS - GREASE
CAUSE:

COMPLETE WET SERVICE. OIL, FUEL, GREASE.

CORRECTION:

- DRAINED ENGINE OIL.
- REPLACED OIL FILTER.
- REPLACED FUEL FILTER AND WATER SEPARATOR.
- REFILLED OIL TO SPEC.
- RAN UNIT, RECHECKED OIL LEVELS.
- TOPPED UP OIL TO SPEC.
- GREASED UNIT, COMPLETED GENERAL INSPECTION FOR DEFECTS.
- RECORDED ANY FOUND.

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

and critical and that all warranty claims are subject to change based on the maintained of a subject to that the maintained of a subject to the subject to the maintained of a subject to the subject to							
x	DATE						
CUSTOMER: X	DATE						



432 Corduroy Road Vars, ON K0A 3H0 P:(613)443-5369 F:(613)443-5340

KINGSTON

191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080

PETERBOROUGH

810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848 **THUNDER BAY** 2730 W. Arthur St Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



					Ta	x ID Dat	e: Tax	(ID: Page	3 0	of 7
YEAR		MAKE / MODEL	VIN	ī		LIC	CENSE	MILEAGE		AUTH
2012	K	Kenworth / T170	2XKHDN9X60	CM95627	5	PA5	51432	325111K		#
DEL DATE		OPEN DATE / TIME	ENGINE MODEL	/ SERIA	L#	P.O.	NUMBER	COMPLETE		UNIT/STOCK
01-16-12	0.	3-05-24/07:10AM	PX-8 / 73	3303134			#	05-31-24	1	KW-12
DEL MILEAGE		MEMO			TRANSMISSION MODEL/SERIAL #			S	ERVICE WRITER	
					FULLER FRO11210C 10-SPEED			GSL*GSL		
					CONCEPT 2 / K0868821					
ENGINE HO	OURS	7761 0	REEFER HOURS		0 0		STBY	HOURS		0 0

- SERVICE COMPLETE.

TOTAL LABOR 470.00 TOTAL PARTS 338.52

Qty	Part Number	Description	List	Unit	Extended
1	FF5636FLG	FILTER-FU	51.14	38.87	38.87
1	FF5636FLG&	F.E.T.	0.50	0.50	0.50
1	FS1003FLG	SEPARATOR	83.32	63.32	63.32
1	FS1003FLG&	F.E.T.	1.00	1.00	1.00
1	264400	AF-400-2	18.52	11.50	11.50
22	222290-990C	CHV DELO	144.98	6.59	144.98
1	313	BRAKE CLN	4.98	4.36	4.36
1	LF9009FLG	FILTER-OI	88.97	68.39	68.39
1	LF9009FLG&	F.E.T.	1.33	1.33	1.33
1	66261074700MSC	NON-WOVEN	5 23	4 27	4 27

10 CUSTOMER STATES THERE IS AN AIR LEAK PRESENT - AIR TANKS DRAINED AFTER 20 MIN OF SITTING - PLEASE INSPECT AND REPORT CAUSE:

NO FAULTS FOUND.

CORRECTION:

- AIRED UP UNIT.
- CHECKED AIR SYSTEMS FOR GOOD OPERATION, ALL OKAY.
- INSPECTED FOR AUDIBLE AND VISIBLE AIR LEAKS, NONE FOUND.
- CHECKED AIR SYSTEM WITH SOAP WATER, NO LEAKS FOUND, NO PRESSURE DROP.
- DIAG COMPLETE, NO FAULTS FOUND.

TOTAL LABOR

112.80

11 2 BUNK A/C LINES LEFT HANGING ON PASSANGER SIDE OF ENGINE - REMOVE

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

I understand that all warranty claims are subject to change based on the manufacturer's discretion. I assume full responsibility for all necessary repair expenses upon claim rejection.					
X	DATE				
CUSTOMER: X_	DATE				



432 Corduroy Road Vars, ON K0A 3H0 P:(613)443-5369 F:(613)443-5340 KINGSTON

191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080 **PETERBOROUGH**

810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848 **THUNDER BAY** 2730 W. Arthur St Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



					Та	x ID Date: Ta	x ID: Page	9 4 c	of 7
YEAR		MAKE / MODEL	VIN	ī		LICENSE	MILEAGE		AUTH
2012	K	Cenworth / T170	2XKHDN9X60	2XKHDN9X6CM956275		PA51432	325111K		#
DEL DATE	C	OPEN DATE / TIME	ENGINE MODEL	/ SERIA	L#	P.O. NUMBER	COMPLETE		UNIT/STOCK
01-16-12	03	3-05-24/07:10AM	PX-8 / 73	3303134		#	05-31-24	1	KW-12
DEL MILEAGE		MEMO			TRAI	NSMISSION MODE	L/SERIAL #	S	ERVICE WRITER
			FULLER		LER FRO112100	ER FRO11210C 10-SPEED		GSL*GSL	
					CONCEPT 2 / K0868				
ENGINE HO	OURS	7761.0	REEFER HOURS		0.0	STB	Y HOURS		0.0

LINES

CAUSE:

CUSTOMER REQUESTS TO LEAVE DISCONNECTED LINES ON UNIT.

CORRECTION:

- LINES SECURED OUT OF WAY, READY FOR FUTURE CONNECTION TO BUNK A/C SYSTEM.

TOTAL LABOR 0.00

12 FIND RIDE HEIGHT SPECS AND ADJUST TO PROPER RIDE HEIGHT CAUSE:

ADJUSTED UNIT TO PROPER RIDE HEIGHT.

CORRECTION:

- CONFIRMED BUILD SPECS AND CURRENT UNIT SETUP.
- ADJUSTED RIDE HEIGHTS TO SPEC.
- REPAIR COMPLETE.

TOTAL LABOR

131.60

14 RESEAL OIL COOLER

CAUSE:

OIL COOLER LEAKING.

CORRECTION:

- DRAINED COOLANT.
- REMOVED AIR-TO-AIR PIPE, HOSE AND AIR INTAKE FROM TURBO.
- REMOVED ALTERNATOR, BRACKET AND EGR COOLANT PIPE.
- REMOVED OIL COOLER.
- CLEAN COOLER, COOLER COVER AND MATING SURFACES.
- REINSTALL COOLER AND COVER.
- REINSTALL EGR PIPE, ALTERNATOR AND BELTS.

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

and the same the same to the same to the same that the same that the same that the same the same the same the same the same that								
X	DATE							
CUSTOMER: X	DATE							



432 Corduroy Road Vars, ON K0A 3H0 P:(613)443-5369 F:(613)443-5340

KINGSTON

191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080

PETERBOROUGH

810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848

THUNDER BAY 2730 W. Arthur St Thunder Bay, ON P7K 4

Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



Tax ID Date: Tax ID: Page 5 of 7 VIN YEAR MAKE / MODEL LICENSE MILEAGE AUTH 2012 Kenworth / T170 2XKHDN9X6CM956275 PA51432 325111K # OPEN DATE / TIME ENGINE MODEL / SERIAL # P.O. NUMBER COMPLETE DEL DATE UNIT/STOCK 03-05-24/07:10AM 73303134 05-31-24 01-16-12 PX-8 / KW - 12DEL MILEAGE TRANSMISSION MODEL/SERIAL # SERVICE WRITER MEMO FULLER FRO11210C 10-SPEED GSL*GSL

ENGINE HOURS 7761.0 REEFER HOURS 0.0 STBY HOURS 0.0

- FILLED COOLANT, PRESSURE TESTED, CONFIRMED NO LEAKS AT COOLER.

- REPAIR COMPLETE.

TOTAL LABOR
TOTAL PARTS

1,560.40 91.91

CONCEPT 2 / K0868821

Qty	Part Number	Description	List	Unit	Extended
1	23631MSC	H S TUBIN	1.15	0.77	0.77
1	3918174CUM	GASKET,OI	33.29	31.23	31.23
1	3929011CUM	GASKET, LU	42.44	39.81	39.81
1	5443707CUM	GASKET, CO	13.97	13.10	13.10
4	D39116MSC	GR.8HXCAP	4.32	1.08	4.32
4	39655MSC	GR. C-NE8	1.32	0.33	1.32
8	36705MSC	HARDENED	1.36	0.17	1.36

15 INSPECT A/C OPERATION - REPLACE HVAC HEAD CAUSE:

FAULTY HVAC CONTROLLER

CORRECTION:

- CONFIRMED A/C CLUTCH NOT ENGAGING.
- DIAG NO SIGNAL TO RELAY.
- TRACE TO HVAC CONTROLLER FAULTY/DEFECTIVE.
- REMOVED CONTROLLER, INSTALLED NEW.
- CONFIRMED PROPER SIGNAL AND OPERATION.
- CLUTCH NOW COMING ON AS NEEDED.
- REPAIR COMPLETE.

TOTAL LABOR 564.00
TOTAL PARTS 494.05

QUOTE NUMBER - 0205 EXPIRATION DATE - 04-12-2024 QUOTE TITLE - 0s55614

I understand that all warranty claims are subject to change based on the manufacturer's discretion. I assume full responsibility for all necessary repair expenses upon claim rejection.

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

x	DATE
CUSTOMER: X	DATE



OTTAWA 432 Corduroy Road Vars, ON K0A 3H0

P:(613)443-5369 F:(613)443-5340

KINGSTON

191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080

PETERBOROUGH

810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848 **THUNDER BAY** 2730 W. Arthur St Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



					<u>ı a</u>	x ID Date: Ta	x ID: Page	6 of 7
YEAR		MAKE / MODEL	VIN	1		LICENSE	MILEAGE	AUTH
2012	K	enworth / T170	2XKHDN9X60	CM95627	5	PA51432	325111K	#
DEL DATE	0	PEN DATE / TIME	ENGINE MODEL	/ SERIA	.L #	P.O. NUMBER	COMPLETE	UNIT/STOCK
01-16-12	0.3	3-05-24/07:10AM	PX-8 / 73	3303134		#	05-31-24	KW-12
DEL MILEAGE		MEMO			TRAI	NSMISSION MODE	L/SERIAL #	SERVICE WRITER
					FULI	LER FRO11210C	10-SPEED	GSL*GSL
					CONCEPT 2 / K0868821			
ENGINE HO	OURS	7761.0	REEFER HOURS		0.0	STBY	Y HOURS	0.0

Qty	Part Number	Description	List	Unit	Extended
1	CP1001	CONTROL-C	705.79	494.05	494.05

17 PERFORM CLUTCH ADJUSTEMENT - REQUESTED BY TIM CAUSE:

COMPLETE CUSTOMER REQUESTED CLUTCH ADJUSTMENT.

CORRECTION:

- ADJUSTED CLUTCH TO BRING AREA OF CONTACT LOWER IN PEDAL TRAVEL.
- ROAD TEST SUCCESSFUL, NO LEAKS, ALL WORKING OKAY.
- ADJUSTMENT COMPLETE.

TOTAL LABOR

188.00

19 SERVICE CALL - 417 WESTBOUND - BEFORE PIPERVILLE ROAD CAUSE:

SERVICE CALL FOR CUSTOMER REPORTED ENGINE ISSUES.

CORRECTION:

CORRECTION:

- LOAD TOOLS AND TRAVEL TO LOCATION.
- ARRIVED ON SITE TO CUSTOMER VEHICLE, CONNECTED TO UNIT AND DOWNLOADED SNAPSHOT.
- FOUND INACTIVE CODES.
- CHECKED OIL LEVELS, ALL OKAY.
- OPERATOR REPORTS HEAVY NOISE FROM ENGINE ON START UP.
- HAD OPERATOR START UNIT, CONFIRMED NOISE FROM ENGINE, BOTTOM AREA.
- UNIT BEING TOWED TO SHOP FOR FULL INSPECTION.

TOTAL LABOR

on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

1,109.20

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges

and the state of t				
X	DATE			
CUSTOMER: X	DATE			



OTTAWA 432 Corduroy Road Vars. ON K0A 3H0

Vars, ON K0A 3H0 P:(613)443-5369 F:(613)443-5340 KINGSTON 191 Dalton Ave Kingston, ON K7K 6C2 P:(613)544-1212 F:(613)544-4080 PETERBOROUGH 810 Technology Dr. Peterborough, ON K9J 6X7 P:(705)742-4747 F:(705)742-4848 **THUNDER BAY** 2730 W. Arthur St Thunder Bay, ON P7K 4V1 P:(807)939-2424 F:(807)939-1955

INVOICE DATE: 05-31-24

Check out our new website at www.kenworthontario.com

CUSTOMER INVOICE
Work
Order: OS55614

Customer: 269164

R&B TRUCKING INC. 4780 FRANK KENNY ROAD Ship To:

R&B TRUCKING INC.



Tax ID Date: Page 7 of 7 Tax ID: VIN YEAR MAKE / MODEL LICENSE MILEAGE AUTH PA51432 2012 Kenworth / T170 2XKHDN9X6CM956275 325111K # OPEN DATE / TIME ENGINE MODEL / SERIAL # COMPLETE UNIT/STOCK DEL DATE P.O. NUMBER 03-05-24/07:10AM 73303134 05-31-24 01-16-12 PX-8 / KW-12 DEL MILEAGE MEMO TRANSMISSION MODEL/SERIAL # SERVICE WRITER FULLER FRO11210C 10-SPEED GSL*GSL CONCEPT 2 / K0868821 ENGINE HOURS STBY HOURS 7761.0 REEFER HOURS 0.0 0.0

LABOR	5 , 846.80
PARTS	989.18
SUBLETS	0.00
SUPPLIES	233.88
FREIGHT	0.00
SVC-MILEAGE	0.00
MISCELLANEOUS	0.00
COUPON	0.00

SUBTOTAL 7,069.86 H.S.T. 857754931 919.08 CHARGE 7,988.94

Wheel nuts must be re-torqued within 100km after installation

TERMS: Net due within 30 days following the purchase date or interest will be charged at the rate of 24% per annum. I agree Kenworth Ontario is not liable for down time. I have read, understand and agree with all the charges on this invoice. I agree to pay all collection fees, attorney fees, and all other legal costs incurred by Kenworth Ontario should any matter related to this invoice be referred to an attorney.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of the repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

X	DATE
CUSTOMED: Y	DATE

I understand that all warranty claims are subject to change based on the manufacturer's discretion. I assume full responsibility for all necessary repair expenses upon claim rejection.