



DIESEL VEHICLE INSPECTION REPORT

VEHICLE OWNER INFORMATION			Date of Test 02/17/2026
Name MAYRA LUCIA MIRANDA FERNANDEZ			
Address 3945 W EVANS AVE			
City DENVER	State CO	Zip Code 80219	

EMISSIONS TEST FACILITY INFORMATION			
Station Number 6061	Station Name Al's Front Range Diesel	Serial # 6061031068	
Inspection Cost \$ 135	Station Address 1115 Bowen Cir.		
Longmont, CO 80501			

VEHICLE INFORMATION			
Vehicle Identification Number 3ALACXFC2KDKU9131			
Model Year 2019	Vehicle Make FRHT	Vehicle License Plate XXU9131	
GVWR 33000	Vehicle Class HD	Non CO. License Plate NO	
# of Cylinders 6	Engine Make CUMM	Engine Type TURBO	Odometer 223896
Transmission Type AUTO	Vehicle smoke repairs last 60 days?	NO	DR2365 NO

FIRST TEST		Inspector Number 12237	AFTER REPAIRS TEST		Inspector Number
Heavy duty vehicle dynamometer lug down test		Heavy duty vehicle dynamometer lug down test			
Snap 0% OPACITY		Snap			
Zero Shift 0% OPACITY		Zero Shift			
Engine Rate 0% OPACITY		Engine Rate			
90% 0% OPACITY		90%			
80% 0% OPACITY		80%			
70% 0% OPACITY		70%			
Zero Shift 0% OPACITY		Zero Shift			
Results PASS		Results			

EMISSIONS CONTROL SYSTEMS			FIRST	FINAL	REPAIR INFORMATION
Pump Seals Air Fuel Adjustment			NA		Fail Repair Cost \$ 0.00
Boost Compensation / Aneroid			NA		Re-insp. Cost \$
Electronic Engine Controls			PASS		Date of Retest
Trap / Catalytic Converter			PASS		
Positive Crankcase Ventilation System			NA		
Exhaust Gas Recirculation System			PASS		

OVERALL RESULTS		CERTIFICATE OF EMISSIONS COMPLIANCE		
Initial Test PASS		Date Of Test 02/17/2026	Test Results PASS	
Retest		VIN 3ALACXFC2KDKU9131	GVWR 33000	
Waiver		Verification # 6061352891	CDOR COLORADO Department of Revenue	