



Commercial Vehicle Inspection Report

Decal Number: GC81548
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21243427

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	59	Lining (Shoe)	18	16	Drum		
2	74	20	Lining (Shoe)	16	20	Drum		
3	37	20	Lining (Shoe)	17	20	Drum		
4	58	71	Lining (Shoe)	18	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BARBEAU-PAWSON, QUINN JOSEPH

Road Test Date: _____ Road Tester: _____
Signature: 

This Inspection Report was submitted to CVSE on 2025-Feb-20 02:12 PM PST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.