

h09-1



Commercial Vehicle Inspection Report

Decal Number: GH48926
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21379673

Inspection Result:
PASS

FACILITY: AMS TRUCK REPAIRS LTD. / S11890
INSPECTOR: Spasiuk, Ryan / 301380
WORK ORDER #: 1474
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Jun-02 11:31 AM PDT
INSP. COMPLETE: 2025-Jun-05 11:32 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 50290B
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2007
MAKE: DOEPKER
MODEL:
REGI: 03621744
UNIT/FLEET#: 671
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2DEHBFZ3171021370
OWNER/LESSEE NAME: CANUSA TRANSPORTATION LTD, CANUSA
ADDRESS: PO BOX 1080, Osyoos, British Columbia, V0H1V0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) -Replaced #2 axle RH air bag (worn). -Replaced worn #1 axle LH shock.
Section 3 - Brake System	Repaired (same day) -Replaced #1 axle LH slack adjuster, cam tube bushings and cam shaft. -Replaced #2 axle RH slack adjuster.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Repaired multiple burnt out lights and broken wiring.
Section 7 - Electrical System	Repaired (same day) Repaired broken Abs wires on #1 axle RH side.
Section 8 - Frame and Body	Repaired (same day) Welded cracks on trailer deck rails.
Section 9A - Tires	Repaired (same day) Replaced worn tires #3 axle RH side.
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left		Right		Tire Tread Depth (mm)			
				Left	Right	Outer L	Inner L	Inner R	Outer R	Steering	
1	Clamp	30	Automatic	45	35	4.5	3.25	8.7	8.75		
2	Clamp	30	Automatic	30	32	9	12.3	12.25	12		
3	Clamp	30	Automatic	30	40	11.3	11	2	3		

Comment: Replaced #3 axle RH tire set.

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	35
2	50	70
3	50	55

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	12	8
Lining (Shoe)	11	11

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor/Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Spasiuk, Ryan
Road Test Date: _____
Signature: _____ Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-05 11:33 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

JVSE014
6/5/2025 11:33:56 AM PDT



Commercial Vehicle Inspection Report

Decal Number: GH48927
 Decal Expiry Date: 2026-Jun-30
 Inspection Number: 21379747

Inspection Result:
PASS

209-2

FACILITY: AMS TRUCK REPAIRS LTD. / S11890
 INSPECTOR: Spasiuk, Ryan / 301380
 WORK ORDER #: 1475

INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual

INSP. START: 2025-Jun-01 08:00 AM PDT
 INSP. COMPLETE: 2025-Jun-02 01:46 PM PDT

VEHICLE JUR: British Columbia
 PLATE #: 50291B

REGI: 03621783
 UNIT/FLEET#: 672

VIN: 2DEHBFA2X71021371
 OWNER/LESSEE NAME: CANUSA TRANSPORTATION LTD, CANUSA

LICENCED GVW(kg): 999999
 VEHICLE YEAR: 2007

MAKE: DOEPKER
 MODEL:

BODY STYLE: Flat Deck Trailer
 ODOMETER:
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE:

ADDRESS: PO BOX 1080
 Osoyoos, British Columbia
 V0H1V0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Replaced multiple burnt out clearance lights.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Welded cracks on deck frame rails.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	32	11.4	11.2	11.8	12	
2	Clamp	30	Automatic	35	33	11.4	12.5	12.5	8.4	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right		Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	80	45		Lining (Shoe)	10	17	Drum		
2	70	60		Lining (Shoe)	14	12	Drum		
Comment:				Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____

Inspector: Spasiuk, Ryan Signature: _____

This Inspection Report was submitted to CVSE on 2025-Jun-05 11:46 AM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement

CVSED014
 6/5/2025 11:48:27 AM PDT