



Commercial Vehicle Inspection Report

Decal Number: GP56204
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21889038

Inspection Result:
PASS

FACILITY:	Walkers Repair Centre / S20307	INSP. TYPE:	Complete	INSP. START:	2026-Aug-18 06:27 PM MDT
INSPECTOR:	SCHAGER, ALBIN CARL / 106733	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Aug-20 06:28 AM MDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	14915309	VIN:	2A9203635TA003937
PLATE #:	18896L	UNIT/FLEET#:		OWNER/LESSEE NAME:	Contracting LTD, CS McLean
LICENCED GVW(kg):	0	BODY STYLE:	Dump Trailer	ADDRESS:	PO Box 176, 4819 Crescentwood DR Edgewater, British Columbia V0A1E0, Canada
VEHICLE YEAR:	2026	ODOMETER:			
MAKE:	ARNES	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	36
2	Clamp	30	Automatic	35	34
3	Clamp	30	Automatic	36	38

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14	14	15	15	
14	14	12	14	
5	12	7	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	60	60
3	60	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	15	15
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SCHAGER, ALBIN CARL Signature: _____

This Inspection Report was submitted to CVSE on 2026-Aug-20 07:28 AM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement
CVSE0014
8/20/2026 7:29:50 AM MDT



Commercial Vehicle Inspection Report

Decal Number: GP56205
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21889041

F12-6.
Inspection Result:
PASS

FACILITY:	Walkers Repair Centre / S20307	INSP. TYPE:	Complete	INSP. START:	2026-Aug-18 05:36 PM MDT
INSPECTOR:	SCHAGER, ALBIN CARL / 106733	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Aug-20 06:36 AM MDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	14915312	VIN:	2A9202920TA003938
PLATE #:	18895L	UNIT/FLEET#:		OWNER/LESSEE NAME:	Contracting LTD, CS McLean
LICENCED GVW(kg): 0		BODY STYLE:	Dump Trailer	ADDRESS:	PO Box 176, 4819 Crescentwood DR
VEHICLE YEAR:	2026	ODOMETER:			Edgewater, British Columbia
MAKE:	ARNES	HUB ODOMETER:			V0A1E0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Repair right tail light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) #2 right inside flat tire
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	36	10	8	14	14	
2	Clamp	30	Automatic	36	37	10	10	9	9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	50	60	Lining (Shoe)	17	15	Drum		
2	50	50	Lining (Shoe)	17	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SCHAGER, ALBIN CARL Signature: _____

This Inspection Report was submitted to CVSE on 2026-Aug-20 07:36 AM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/20/2026 7:36:50 AM MDT