



Commercial Vehicle Inspection Report

Decal Number: GP56207
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21889048

712-8
Inspection Result:
PASS

FACILITY: Walkers Repair Centre / S20307 INSP. TYPE: Complete INSP. START: 2026-Aug-18 06:55 PM MDT
INSPECTOR: SCHAGER, ALBIN CARL / 106733 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Aug-20 06:55 AM MDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14457395 VIN: 2A9203636RA003034
PLATE #: 41954L UNIT/FLEET#: 3034 OWNER/LESSEE NAME: Contracting LTD, CS McLean
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: PO Box 176, 4819 Crescentwood DR
VEHICLE YEAR: 2024 ODOMETER: Edgewater, British Columbia
MAKE: ARNES HUB ODOMETER: V0A1E0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	34
2	Clamp	30	Automatic	32	33
3	Clamp	30	Automatic	32	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14	14	14	14	
14	14	14	11	
11	11	11	11	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	60
2	40	40
3	40	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	15
Lining (Shoe)	19	19
Lining (Shoe)	19	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SCHAGER, ALBIN CARL

Signature: _____

This Inspection Report was submitted to CVSE on 2026-Aug-20 07:56 AM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/20/2026 7:56:41 AM MDT



Commercial Vehicle Inspection Report

Decal Number: GP56208
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21889052

F12-9
Inspection Result:
PASS

FACILITY: Walkers Repair Centre / S20307 INSP. TYPE: Complete INSP. START: 2026-Aug-18 07:01 PM MDT
INSPECTOR: SCHAGER, ALBIN CARL / 106733 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Aug-20 06:01 AM MDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14457398 VIN: 2A9202921RA003035
PLATE #: 41955L UNIT/FLEET#: 3035 OWNER/LESSEE NAME: Contracting LTD, CS McLean
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: PO Box 176, 4819 Crescentwood DR
VEHICLE YEAR: 2024 ODOMETER: Edgewater, British Columbia
MAKE: ARNES HUB ODOMETER: V0A1E0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	33	34
2	Clamp	30	Automatic	34	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	12	8	8	
14	9	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	65
2	75	75

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	12	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SCHAGER, ALBIN CARL

Signature: _____

This Inspection Report was submitted to CVSE on 2026-Aug-20 08:02 AM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/20/2026 8:02:30 AM MDT