E11-9

Commercial Vehicle Inspection Report

Decal Number: GP55743
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21943308

Inspection Result: **PASS**

FACILITY:	RIVERSIDE REPAIRS / S5662	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Oct-02 01:30 PM PDT
INSPECTOR:	LOOMER, SCOTT / 301675	**INSP. CLASS:**	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Oct-05 09:36 AM PDT
WORK ORDER #:		**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	10660078	**VIN:**	2DELGFZ2XD1030129
PLATE #:	88235U	**UNIT/FLEET#:**	941A 10060A	**OWNER/LESSEE NAME:**	Newlands Log Hauling Ltd, Newlands
LICENCED GVW(kg):	999999	**BODY STYLE:**	LOGGING TRAILER	**ADDRESS:**	Po Box 286
VEHICLE YEAR:	2013	**ODOMETER:**			Fort St James, British Columbia
MAKE:	DOEPKER	**HUB ODOMETER:**			V0J 1P0, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	**Repaired (same day)**	Replace service lines to axle 2 brake pots
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	**Repaired (same day)**	Repair brake lights, tail lights, marker lights and license plate light
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Repaired (same day)**	Replace landing gear crank handle
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	35
2	Clamp	30	Automatic	35	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	10	9	14	
9	13	11	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	29	44
2	46	39

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	18
Lining (Shoe)	19	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: LOOMER, SCOTT **Signature:** Scott Loomer

This Inspection Report was submitted to CVSE on 2026-Oct-05 09:37 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/5/2026 9:37:25 AM PDT