



Commercial Vehicle Inspection Report

Decal Number: GH81682
 Decal Expiry Date: 2027-Mar-31
 Inspection Number: 21699580

Inspection Result:
PASS

FACILITY: CULLEN WESTERN STAR TRUCKS LTD / S5079
 INSPECTOR: SEROKA, NIKOLAI / 301041
 WORK ORDER #: R421621635

INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual

INSP. START: 2026-Mar-17 12:38 PM PDT
 INSP. COMPLETE: 2026-Mar-17 03:49 PM PDT

VEHICLE JUR: Alberta
 PLATE #: 6NL575
 LICENCED GVW(kg): 1
 VEHICLE YEAR: 1995
 MAKE: FONTAINE
 MODEL: TRAILER

REGI: UNIT/FLEET#: 23C
 BODY STYLE: Trailer
 ODOMETER:
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE: Not Applicable

VIN: 2BGD06045000S4151
 OWNER/LESSEE NAME: LTD. SPRUCE HOLLOW HEAVY HAUL
 ADDRESS: PO BOX 28045 RPO MAHOGANY
 CALGARY, Alberta
 T3M3C9, Canada

520-13

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE LEAKING RELAY VALVE, REPLACE FAILED BRAKE POTS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.8	31.8	17	17	17	17	
2	Clamp	30	Automatic	31.8	44.5	17	17	17	17	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	60	Lining (Shoe)	14	14	Drum		
2	55	55	Lining (Shoe)	16	16	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: SEROKA, NIKOLAI
 Road Test Date:
 Signature:
 Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-17 03:50 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQV/P at the Commercial Vehicle Safety Enforcement

CVSE014
 3/17/2026 3:50:32 PM PDT



Commercial Vehicle Inspection Report

Decal Number: GH81682

Decal Expiry Date: 2027 Mar 31

Inspection Number: 21699580

Inspection Result

PASS

S20-15

FACILITY: CALLEN WESTERN STATE TRUCKS
INSPECTOR: SEROKA, NIKOLAI
WORK ORDER #: 161021635

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2026-Mar-17 12:38 PM PDT
INSP. COMPLETE: 2026-Mar-17 03:49 PM PDT

VEHICLE ID#: 2026
PLATE #: 458277
IDENTIFIED GVW (kg):
VEHICLE YEAR: 2026
MAKE: HUNTANE
MODEL: DEALER

REGI: 23C
UNIT/FLEET#: Trailer
BODY STYLE: Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

VIN: 2026Y0021400258151
OWNER/LESSEE NAME: LTD. SPRUCE HOLLOW HEAVY HAUL
ADDRESS: PO BOX 28045 RPO MAJOGANY
CALGARY, Alberta
T3M3C9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE LEAKING RELAY VALVE, REPLACE FAILED BRAKE POTS
Section 3B - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.8	31.8	17	17	17	17	
2	Clamp	30	Automatic	31.8	44.5	17	17	17	17	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	60	Lining (Shoe)	14	14	Drum		
2	55	55	Lining (Shoe)	16	16	Drum		

Inspection Comments: Has this Vehicle been road tested? No
Inspector: SEROKA, NIKOLAI
Road Test Date: [Signature]
Road Tester: [Signature]

This inspection report was submitted to CVSE on 2026-Mar-17 03:50 PM PDT
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 29 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and the vehicle's registration under the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and assigned inspection facilities). If you have any questions about the collection of the information, you may contact the BC Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CVSE-18
3-17-2024 2:50:25 PM PDT