



Commercial Vehicle Inspection Report

Decal Number: GP36389
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21887636

LV5-6

Inspection Result:

PASS

FACILITY:	Inland Truck & Equipment Ltd / S20220	INSP. TYPE:	Complete	INSP. START:	2026-Aug-18 05:52 PM PDT
INSPECTOR:	LAVOIE, SHAYAN / 301320	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Aug-18 07:52 PM PDT
WORK ORDER #:	RA112001067	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	03575854	VIN:	2FWJAZCV86AV47480
PLATE #:	3306JV	UNIT/FLEET#:	561	OWNER/LESSEE NAME:	Burnco Rock Products Ltd, Burnco Rock Products Ltd
LICENCED GVW(kg):	47300	BODY STYLE:	Truck Tractor	ADDRESS:	5324 RIVERBEND DR
VEHICLE YEAR:	2006	ODOMETER:	149870 KM		Burnaby, British Columbia
MAKE:	STERLING	HUB ODOMETER:			V3N 4P8, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed with Caution Driveline between transmission and differential has play but is still within specification - monitor.
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	27	27
2	Clamp	30L	Automatic	36	33
3	Clamp	30L	Automatic	31	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
14			15	✓
8	8	8	8	
8	8	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	46	47
2	57	63
3	64	58

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	16	16
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

Inspector: LAVOIE, SHAYAN

This Inspection Report was submitted to CVSE on 2026-Aug-18 07:53 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/18/2026 7:53:46 PM PDT