



Commercial Vehicle Inspection Report

Decal Number: GA68786
Decal Expiry Date: 2025-Mar-31
Inspection Number: 20859596

Inspection Result:
PASS

FACILITY: PENSKE TRUCK LEASING INC / S5242
INSPECTOR: JONES, RYAN DANIEL / 202076
WORK ORDER #: 2205-303999
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Mar-19 03:00 PM PST
INSP. COMPLETE: 2024-Mar-19 06:30 PM PST
P53-24

VEHICLE JUR: British Columbia
PLATE #: 18719U
REGI: 11845740
UNIT/FLEET#: 170081
VIN: 1UYVS3530HU887402
OWNER/LESSEE NAME: PENSKE TRUCK LEASING CANADA, (LESSOR), ALIMENTS SAPUTO LIMITED(LESSEE)
LICENCED GVW(kg): 999999
BODY STYLE: Van Trailer
ADDRESS: 1889 KINGSWAY AVE, 2916 NORELAND
VEHICLE YEAR: 2017
MAKE: UTILITY
MODEL:
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
Port Coquitlam, British Columbia
V3C1S9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) #1 AXLE D/S&P/S SHOCKS REPLACED, #2 AXLE, D/S&P/SHOCKS WERE REPLACED SAME DAY
Section 3 - Brake System	Repaired (same day) D/S, #1 AXLE REPLACED LINER, DRUM, REPLACED P/S LINER, DRUM. D/S&P/S #2 REPLACED WHEEL SEAL, LINER, DRUM, S-CAM BUSHING,
Section 3A - Air Brakes	Repaired (same day) D/S, #1 AXLE REPLACED LINER, DRUM, REPLACED P/S LINER, DRUM. D/S&P/S #2 REPLACED WHEEL SEAL, LINER, DRUM, S-CAM BUSHING.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) REPLACED D/S, INNER&OUTER TIRES AND RIMS
Section 9B - Wheels	Repaired (same day) REPLACED D/S, INNER&OUTER TIRES AND RIMS
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	35	11.9	12.7	7.1	7.9	
2	Clamp	30	Automatic	35	35	7.1	8.7	10.3	11.1	
3	Clamp	30	Automatic	35	35	15.1	15.1	14.3	15.1	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	20	20	Lining (Shoe)	19	19	Drum		
2	20	20	Lining (Shoe)	19	19	Drum		
3	90	40	Lining (Shoe)	18	12	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: JONES, RYAN DANIEL
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Mar-19 06:49 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014
3/19/2024 6:51:34 PM PST