



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PX17676
Decal Expiry Date: 2025-Feb-28
Inspection Number: 21049481

Inspection Result:
PASS

AIS-1

FACILITY: NORTHERN B.C. TRUCKERS /
N5398
INSPECTOR: PEREGOODOFF, DAVID JAMES /
112485
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2024-Aug-21 07:00 AM MST
INSP. COMPLETE: 2024-Aug-21 08:30 AM MST

VEHICLE JUR: British Columbia
PLATE #: VV9651
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2015
MAKE: KENWORTH
MODEL:

REGI: 14538969
UNIT/FLEET#: 201
BODY STYLE: Truck Tractor
ODOMETER: 1199601 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

VIN: 1XKDP4TX1FJ971660
OWNER/LESSEE NAME: ARTACIA CONTRACTING LTD.,
ADDRESS: 12234 PACIFIC AVE
Fort St John, British Columbia
V1J8A5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) FAN HUB AIR LEAK
Section 2 - Suspension	Repaired (same day) #2,3,4 L+R LOOSE SHOCKS
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) #2,3,4 AIR LINES RUBBING
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) L/P LIGHT, MIDSHIP MARKER L+R
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) L REAR FENDER LOOSE
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	28	30
2	Clamp	30	Automatic	37	35
3	Clamp	30	Automatic	35	38
4	Clamp	30	Automatic	40	37

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
16			17	✓
17	18	15	18	
10	12	10	11	
23	23	21	23	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/26/2024 12:50:39 PM MST



Commercial Vehicle Inspection Report



Inspection Number: PX17676
Local Expiry Date: 2025-Feb-28
Inspection Number: 21049481

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	67	53	Lining (Shoe)	14	16	Drum		
2	70	65	Lining (Shoe)	14	14	Drum		
3	72	62	Lining (Shoe)	14	14	Drum		
4	75	78	Lining (Shoe)	14	14	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

Inspector: PEREGOODOFF, DAVID JAMES
This inspection Report was submitted to CVSE on 2024-Aug-28 12:50 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSED014

8/28/2024 12:50:39 PM MST

DRAFT

Commercial Vehicle Inspection Report

DRAFT INSPECTION
REPORT NUMBER

PLACE DECAL
HERE

DECAL EXPIRY DATE

INSPECTION RESULT: *Passed*
INSPECTION TYPE: *complete*
REASON FOR INSPECTION: *semi annual*
COLLISION REPAIR FACILITY:

WORK ORDER #

INSPECTION START DATE

INSPECTION COMPLETE DATE

REASON NOTE:

TECHNICIAN NAME:

PHONE #:

INSPECTOR'S NUMBER: 112485

INSPECTOR'S NAME: PEREGOODOFF, DAVID JAMES

LICENCE EXPIRY DATE: 31 MAY 2025

FACILITY NUMBER: N5398

FACILITY NAME: NBCTA

INSPECTION CLASS: *truck*

OWNER/
LESSEE: *Artacia Contracting LTD*

ADDRESS: *12234 Pacific Avenue*

CITY: *Fort St John* PROV: *BC* POSTAL CODE: *V1S 8A5*

REGISTRATION #: *14538969* VEH. JURISDICTION: *BC* PLATE: *VV9651*

YEAR: *2015* MAKE: *Kenworth* MODEL:

BODY STYLE: *truck tractor* VIN: *1XKDP4TX1FJ971660*

ODOMETER: *1199601* FUEL TYPE: *D*

UNIT/FLEET #: *201* BRAKE TYPE: *A*

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA
Section 1 - Power Train							Pressure Fuel						
<i>Fan hub air leak</i>							Liquid Propane Gas						
Section 2 - Suspension							Compressed Natural Gas						
<i>#2, 3, 4 LTR loose shocks</i>							Pressure Fuel Inspector's Name & Number						
Section 3 - Hydraulic Brakes							Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: C C C C						
							Size: 24 30 30 30						
							Slack: A A A A						
							Left: 28 27 25 40						
							Right: 30 35 38 37						
Section 3A - Air Brakes							Air Brake Camshaft Rotation Measurement (degrees)						
<i>#2, 3, 4 air lines rubbing</i>							Axle # 1 2 3 4 5 6 7 8 9						
Section 4 - Steering							Left: 67 70 72 75						
							Right: 53 65 62 78						
Section 5 - Instruments, Auxillary Equipment							Brake Lining/Pad Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: C C C C						
							Left: 14 14 14 14						
							Right: 16 14 14 14						
Section 6 - Lamps							<i>lines</i>						
<i>Lp light, midship marker LTR</i>							Rotor/Drum Measurement (mm)						
Section 7 - Electrical System							Axle # 1 2 3 4 5 6 7 8 9						
							Type: 16 18/17 12/10 23/23						
							Left: 17 15/18 20/4 21/23						
							Right: 17 15/18 20/4 21/23						
Section 8 - Body & Frame													
<i>L rear bumper loose</i>													
Section 9 - Tires & Wheels													
Section 10 - Couplers & Hitches													
Section 11 - Other Vehicle Components													

General Inspection Comments:

Inspector's Name *David Peregoodoff*

Signature *[Signature]*

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.
NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement Branch.

CVSE0014 (100615)