

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

GC98820 2025-Jul-31 21000504

T15-25

PASS

FACILITY:	FACILITY: P & H SUPPLIES LTD. / S0397		Complete	INSP. START:	2024-Jun-27 02:30 PM PDT
INSPECTOR: FOLEY, RUSSEL PATRICK / 109458		INSP. CLASS:	Class 3 - Trailer and Semi	-Trailer INSP. COMPLET	E: 2024-Jul-11 01:59 PM PDT
WORK ORDER #:	32470	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	13356833	VIN:	2K9LB35887L052367
PLATE #:	54305J	UNIT/FLEET#:	TR16	OWNER/LESSEE NAME:	West River Holdings, Ltd
LICENCED GVW(kg): 0	BODY STYLE:	Lowbed Trailer	ADDRESS:	10-556 N Nechako Rd
VEHICLE YEAR:	2007	ODOMETER:			Prince George, British Columbia
MAKE:	K-LINE	HUB ODOMETER:			V2K 1A1, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

		FUEL TYPE:	
Vehicle Identification (VIN)		Passed	
Section 1 - Power Train		Not Applicable	
Section 2 - Suspension		Repaired (same day)	Trailing arm cracks
Section 3 - Brake System		Passed	
Section 3A- Air Brakes		Repaired (same day)	Axle 1/2 brakes, 1L slack adjuster rod & snap ring
Section 3H - Hydraulic Brak	es	Not Applicable	
Section 4 - Steering		Not Applicable	
Section 5 - Instruments and Equipment	d Auxiliary	Not Applicable	
Section 6 - Lamps		Repaired (same day)	Left front marker
Section 7 - Electrical System	m ji je i	Passed	
Section 8 - Frame and Body	y	Repaired (same day)	Front crossmember cracked
Section 9A- Tires		Passed	
Section 9B - Wheels		Passed	
Section 10 - Coupling Devi	ces	Repaired (same day)	King pin & boss
Section 11 - Other Vehicle	Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)			Tire Tread Depth (mm)							
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	45	45	10	6	12	13	
2	Clamp	30	Automatic	45	47	11	4	13	10 ~~	
-	- Clamp	30	Automatic	48	45	19	10	8	8	* Agranda in a
Comment:						Comment				

Air Brake Camsh	aft Rotation (deg	rees)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	109	105	Lining (Shoe)	11	8	Drum			
2	118	110	Lining (Shoe)	15	11	. Drum			
3	18	50	Lining (Shoe)	19	17	Drum			
Comment:		Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.				

Inspection Comments:

Has this Vehicle been road tested?

Road Test Date:

FOLEY, RUSSEL PATRICK Signature:

This Inspection Report was submitted to CVSE on 2024-Jul-11 02:00 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities), if you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement CVSE0014

7/11/2024 2:00:40 PM PDT