



Commercial Vehicle Inspection Report

Decal Number: GF48932
Decal Expiry Date: 2025-Sep-30
Inspection Number: 21267310

A06-17

Inspection Result:
PASS

FACILITY: NORTHLAND FLEET SERVICES LTD. / S15630
INSPECTOR: Clark, Thomas William JOHN / 113405
WORK ORDER #: 400-10982
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2025-Mar-07 12:00 PM PDT
INSPECTION COMPLETE: 2025-Mar-07 02:00 PM PDT

VEHICLE JUR: Alberta
PLATE #: L75688
PERMITTED GVW(kg): 63500
VEHICLE YEAR: 2018
MAKE: Mack
MODEL:
REGI:
UNIT/FLEET#: 10043
BODY STYLE: Tractor
ODOMETER: 860613 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1M1AW13Y9JM001281
OWNER/LESSEE NAME: Laprairie Works Oilfield Services, Inc.
ADDRESS: 702-505 2 st sw
Calgary, Alberta
T2P 1N8, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	35	15			15	✓
2	Clamp	30L	Automatic	37	37	24	24	24	24	
3	Clamp	30L	Automatic	36	35	17	17	17	17	
4	Clamp	30L	Automatic	35	36	17	17	17	17	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	35	35	Lining (Shoe)	16	16	Drum			
2	60	60	Lining (Shoe)	14	14	Drum			
3	30	30	Lining (Shoe)	18	18	Drum			
4	30	30	Lining (Shoe)	18	18	Drum			

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this vehicle been road tested? Yes

Inspector: Clark, Thomas William JOHN

Road Test Date: Before inspection

Signature:

Road Tester: Thomas Clark

Thomas Clark

This Inspection Report was submitted to CVSE on 2025-Mar-12 11:29 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

VSE0014

12/2025 11:29:41 AM PDT