



Commercial Vehicle Inspection Report

Decal Number: GD83830
Decal Expiry Date: 2025-Sep-30
Inspection Number: 21058733

Inspection Result:

PASS

FACILITY: NEW MILLENNIUM TIRE CENTRE / S16420
INSPECTOR: AUJLA, BHUPINDER / 300410
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2024-Sep-03 12:00 PM PDT
INSP. COMPLETE: 2024-Sep-03 01:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 36743K

REGI: 13469748
UNIT/FLEET#: 723119

VIN: 1UYVS3530FU023804
OWNER/LESSEE NAME: IHAUL FREIGHT LTD., IHAUL FREIGHT LTD.

LICENCED GVW(kg): 0
VEHICLE YEAR: 2015
MAKE: UTILITY
MODEL:

BODY STYLE: Reefer Van Trailer
ADDRESS: UNIT-105 8047 199 ST
Langley, British Columbia
V2Y 0E2, Canada

ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) AXLE 1 LEFT SIDE AXLE 2 BOTH SIDE AIR BAG CHANGED, AXLE 2 RIGHT SIDE SHOCK CHANGED
Section 3 - Brake System	Repaired (same day) AXLE 2 BOTH SIDE BRAKE PAD CHANGED
Section 3A - Air Brakes	Repaired (same day) AIR LEAK FIXED IN ABS VALVE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxilliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) 3RD AXLE RIGHT SIDE WHEEL SEAL CHANGED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Disc	N/A	Not Applicable	0	0
3	Disc	N/A	Not Applicable	0	0

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8	8	11	11	
7	7	7	7	
8	8	9	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	13	13
Pad	21	21
Pad	13	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor	43.90	40.00
Rotor	44.50	44.20
Rotor	44.00	44.10

Comment:

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: AUJLA, BHUPINDER

Signature:

This Inspection Report was submitted to CVSE on 2024-Sep-03 02:36 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

CVSE014

9/3/2024 2:36:32 PM PDT

