



# Commercial Vehicle Inspection Report

Decal Number: GJ29538  
Decal Expiry Date: 2026-Apr-30  
Inspection Number: 21322888

H19-4  
Inspection Result:  
**PASS**

FACILITY:	NEW WEST TRUCK CENTRES (BC) INC. / S20396	INSP. TYPE:	Complete	INSP. START:	2025-Apr-24 08:50 AM MDT
INSPECTOR:	HUNTER, ANDREW / 301365	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Apr-24 09:50 AM MDT
WORK ORDER #:	1226	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	03131347	VIN:	1HTMMAAM39H064712
PLATE #:	JM4411	UNIT/FLEET#:		OWNER/LESSEE NAME:	OVERLAND WEST FREIGHT LINES, .
PERMITTED GVW(kg):	14500	BODY STYLE:	Van	ADDRESS:	11398 BRIDGEVIEW DRIVE, 11398 BRIDGEVIEW DRIVE Surrey, British Columbia V3R 0C2, Canada
VEHICLE YEAR:	2009	ODOMETER:	428791 KM		
MAKE:	INTERNATNA	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Hydraulic		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Repaired (same day) STEERING REPAIRS
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) LIGHT REPAIRS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) MUDFLAP BRACKET REPAIRS
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	12			13	✓	Pad	12	12	Rotor	36.80	36.80
2	6	7	7	6		Pad	12	12	Rotor	36.20	36.70
Comment:						Comment:			Comment:		

Inspection Comments:  
Has this Vehicle been road tested? No  
Inspector: HUNTER, ANDREW  
Road Test Date:                       
Signature: *Andrew Hunter*  
Road Tester:                     

This Inspection Report was submitted to CVSE on 2025-Apr-24 10:52 AM MDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.