



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GJ26407
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21320547

EN23-1

Inspection Result:

PASS

FACILITY: BABINE TRUCK & EQUIPMENT LTD. / S20188
INSPECTOR: ORSER, DANIEL EDWARD / 112887
WORK ORDER #: 115473
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-Apr-22 01:30 PM PDT
INSP. COMPLETE: 2025-Apr-22 03:44 PM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2022
MAKE: FREIGHTLIN
MODEL:
REGI: 13852908
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 670828 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 3AKJHLD15NDN8498
OWNER/LESSEE NAME: LOMAK BULK CARRIERS CORP., LOMAK
ADDRESS: 6555 PACIFIC ST
Prince George, British Columbia
V2N5S4, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Passed
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Disc	N/A	Not Applicable	0	0	10			13	✓
2	Clamp	30L	Automatic	38.1	38.1	11	11	12	10	
3	Clamp	30L	Automatic	38.1	38.1	14	9	9	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	15	50
3	15	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	13	13
Lining (Shoe)	22	14
Lining (Shoe)	22	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: ORSER, DANIEL EDWARD
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-22 03:47 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. registering carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/22/2025 3:47:13 PM PDT