



Commercial Vehicle Inspection Report

Decal Number: GH78335
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21387467

Inspection Result:
PASS

FACILITY:	CUMMINS SALES AND SERVICE / S16380	INSP. TYPE:	Complete	INSP. START:	2025-Jun-11 01:24 PM PDT
INSPECTOR:	Moody, Hugh Brian / 112507	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jun-11 05:24 PM PDT
WORK ORDER #:	58752	INSP. REASON:	Semi-annual	m23-36	
VEHICLE JUR:	British Columbia	REGI:	13029280		
PLATE #:	50962P	UNIT/FLEET#:	527	OWNER/LESSEE NAME:	TANKERS LOGISTICS INC., TANKERS LOGISTICS INC.
LICENCED GVW(kg):	63500	BODY STYLE:	Tank	ADDRESS:	5022 HIGHWAY 6, PO BOX 193
VEHICLE YEAR:	2020	ODOMETER:	1466266 KM		Burton, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V0G1E0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed with Caution #2 LEFT AND RIGHT SHOCKS REPLACED, #1 RIGHT SHOCK ON ORDER
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repalred (same day) #1 BRAKE CHAMBER REPLACED, #2 RIGHT BRAKE REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed with Caution 1 VISOR LIGHT HALF LEDS OUT, PART ON ORDER
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repalred (same day) WINDSHIELD REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)		Inner R	Outer R	Steering
						Outer L	Inner L			
1	Clamp	24L	Automatic	38	38	11			14	✓
2	Clamp	30L	Automatic	32	32	12	12	13	13	
3	Clamp	30L	Automatic	38	38	13	13	13	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	80
2	90	35
3	60	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	13
Lining (Shoe)	11	20
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Moody, Hugh Brian

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-11 05:29 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/11/2025 5:29:41 PM PDT