



# Commercial Vehicle Inspection Report

Decal Number: GK12736  
Decal Expiry Date: 2026-Feb-28  
Inspection Number: 21457885

F27-1  
Inspection Result:  
**PASS**

FACILITY: ATS MECHANICAL INC. / S10480  
INSPECTOR: BARBEAU-PAWSON, QUINN JOSEPH / 201958  
WORK ORDER #:  
VEHICLE JUR: British Columbia  
PLATE #:  
LICENCED GVW(kg): 63500  
VEHICLE YEAR: 2016  
MAKE: PETERBILT  
MODEL:  
INSP. TYPE: Complete  
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
INSP. REASON: Semi-annual  
INSP. START: 2025-Aug-11 05:50 AM PDT  
INSP. COMPLETE: 2025-Aug-12 03:24 PM PDT  
VIN: 1XPXD49X2GD333490  
OWNER/LESSEE NAME: agri-trans, services ltd  
ADDRESS: 2200 kirtan ave  
Armstrong, British Columbia  
VOE 1B0, Canada  
REGI: 11754096  
UNIT/FLEET#: 550  
BODY STYLE: Truck Tractor  
ODOMETER: 831327 KM  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) replaced abs module-repaired multile abs wiring issues
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) repaired rear licence plate light/ rear markers
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

## Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	13			13	✓
2	Disc	N/A	Not Applicable	0	0	12	12	12	12	
3	Disc	N/A	Not Applicable	0	0	12	13	13	12	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

## Brake Lining/Pad (mm)

## Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	13	13	Rotor	44.00	43.00
2	0	0	Pad	14	15	Rotor	43.00	43.00
3	0	0	Pad	15	15	Rotor	43.00	43.00

Comment:

Comment:

Comment:

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: BARBEAU-PAWSON, QUINN JOSEPH  
Road Test Date: \_\_\_\_\_  
Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Aug-12 03:25 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCPV at the Commercial Vehicle Safety Enforcement

CVSE0014

8/12/2025 3:25:55 PM PDT