



Commercial Vehicle Inspection Report

Decal Number: GK12730
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21452800

F27-2
Inspection Result:
PASS

FACILITY:	ATS MECHANICAL INC. / S10480	INSP. TYPE:	Complete	INSP. START:	2025-Jul-23 04:00 PM PDT
INSPECTOR:	BARBEAU-PAWSON, QUINN JOSEPH / 201958	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-07 01:00 PM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12980412	VIN:	1XPXD49X3LD496031
PLATE #:		UNIT/FLEET#:	570	OWNER/LESSEE NAME:	agri-trans, services ltd
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	2200 kirtan ave
VEHICLE YEAR:	2020	ODOMETER:	604875 KM		Armstrong, British Columbia
MAKE:	PETERBILT	HUB ODOMETER:			V0E 1B0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed with Caution pwc-engine oil leaks forming
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) replaced #2 LH pads
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) repaired licence plate light/rh air cleaner markers
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	12			12	✓
2	Disc	N/A	Not Applicable	0	0	13	13	13	13	
3	Disc	N/A	Not Applicable	0	0	13	13	13	12	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	11	10	Rotor	42.00	42.00
2	0	0	Pad	20	13	Rotor	42.00	43.00
3	0	0	Pad	13	13	Rotor	43.00	43.00
Comment:			Comment: #2lh new			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BARBEAU-PAWSON, QUINN
JOSEPH
Road Test Date:
Signature: _____
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-07 01:26 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/7/2025 1:26:26 PM PDT