



Commercial Vehicle Inspection Report

Decal Number: GJ26710
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21334530

604-1 Inspection Result:
PASS

FACILITY: NOON DAY MOON / S10590 **INSP. TYPE:** Complete **INSP. START:** 2025-May-01 07:00 AM PDT
INSPECTOR: Piper, David Donald JOHN / 101851 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2025-May-01 09:00 AM PDT
WORK ORDER #: 137293 **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 13461733 **VIN:** 1NPCP4TX8MD750584
PLATE #: WM8814 **UNIT/FLEET#:** 752667 **OWNER/LESSEE NAME:** NBC CONTRACTING INC, NBC
LICENCED GVW(kg): 63500 **BODY STYLE:** Truck Tractor **ADDRESS:** 3641 CRESCENT ST PO BOX 561 STN MAIN, 3641 CRESCENT ST PO BOX 561 STN MAIN
VEHICLE YEAR: 2021 **ODOMETER:** 307525 KM **Terrace, British Columbia**
MAKE: PETERBILT **HUB ODOMETER:** V8G4B5, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Disc	N/A	Not Applicable	0	0
2	Disc	N/A	Not Applicable	0	0
3	Disc	N/A	Not Applicable	0	0
4	Disc	N/A	Not Applicable	0	0

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9			10	✓
10	13	12	11	
13	17	13	15	
12	12	12	12	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSD014

5/1/2025 1:05:26 PM PDT



Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	13	12	Rotor	42.73	42.78
2	0	0	Pad	14	15	Rotor	43.46	43.58
3	0	0	Pad	15	14	Rotor	43.73	43.53
4	0	0	Pad	16	14	Rotor	43.34	43.40
Comment:			Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: Piper, David Donald JOHN

Signature:

This Inspection Report was submitted to CVSE on 2025-May-01 01:05 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/1/2025 1:05:26 PM PDT