



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY08910
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21347735

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:
VEHICLE JUR: British Columbia
PLATE #: PA9938
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2013
MAKE: KENWORTH
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-May-11 02:00 PM MST
INSP. COMPLETE: 2025-May-11 03:30 PM MST
REGI: 10551448
UNIT/FLEET#: 243
BODY STYLE: Truck Tractor
ODOMETER: 735968 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1XKDD40X7DR959640
OWNER/LESSEE NAME: MACRO INDUSTRIES, INC
ADDRESS: PO BOX 6781
Fort St John, British Columbia
V1J4J2, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Passed
Section 2 - Suspension Passed
Section 3 - Brake System Not Applicable
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)		Tire Tread Depth (mm)				Steering
				Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	27	28	5				
2	Clamp	30	Automatic	41	42	14	14	12	11	✓
3	Clamp	30	Automatic	40	39	13	13	13	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	48	56
2	69	73
3	62	69

Comment:

Brake Lining/Pad (mm)

Lining/Pad		Left	Right
Lining (Shoe)		18	17.5
Lining (Shoe)		18	19
Lining (Shoe)		19	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: CHRISTIANSON, LESLIE RYAN

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-12 11:21 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE014

5/12/2025 11:21:37 AM MST