



Commercial Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number

PY14332 2026-Jul-31 21426203

Inspection Result:

FACILITY: INSPECTOR: NORTHERN B.C. TRUCKERS' /

CHRISTIANSON, LESLIE RYAN /

106407

INSP. TYPE: INSP. CLASS: INSP. REASON:

Complete

Annual

Class 3 - Trailer and Semi-Trailer

INSP. START:

INSP. COMPLETE:

2025-Jul-10 08:00 AM MST

2025-Jul-10 09:00 AM MST

WORK ORDER #:

VEHICLE JUR: PLATE #:

British Columbia 58289B

LICENCED GVW(kg): 999999

2006

REGI: UNIT/FLEET#:

03528787 337

Lowbed Trailer

VIN: OWNER/LESSEE NAME:

ADDRESS:

2M513131961109901 MACRO INDUSTRIES, INC

PO BOX 6781

Fort St John, British Columbia

V1J4J2, Canada

VEHICLE YEAR: MAKE MODEL :

MANAC

ODOMETER: HUB ODOMETER: BRAKE TYPE: **FUEL TYPE:**

BODY STYLE:

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body Section 9A - Tires Section 9B - Wheels Section 10 - Coupling Devices

Section 11 - Other Vehicle Components

Passed

Not Applicable Passed

Not Applicable Passed Not Applicable

Not Applicable Not Applicable

Passed Passed Passed Passed Passed

> Passed Not Applicable

Air Brake Chamber Time Size and Durch

All brake Chamber Type, Size and Push Rod Stroke (mm)			Tire Tread Depth (mm)							
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	30	31	15	15	14	Outer R	Steering
2	Clamp	30	Automatic	30	28	16	10	939	14	
3	Clamp	30	Automatic	29	31	13	13	10	12	
Comment:						Comment:	13	13	13	

Air Brake Camshaft Rotation (degrees) Axles Left Right				
Left	Right			
59	55			
35	29			
29	31			
	Left 59 35	Left Right 59 55 35 29		

Brake Lining/Pad (mm)		
Lining/Pad	Left	Right
Lining (Shoe)	16	15
Lining (Shoe)	16	22
Lining (Shoe)	14	21
Comment:		

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? Inspector:

No CHRISTIANSON, LESLIE RYAN Road Test Date: Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-15 01:12 PM MST

The inspector's signature above is certification that this vehicle has been inspected to

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

the requirements of the Motor Vehicle Act and Regulations.

7/15/2025 1:13:16 PM MST