



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY14336
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21426505

004-27

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS /
N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Jul-10 12:00 PM MST
INSP. COMPLETE: 2025-Jul-10 01:00 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 97874U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2017
MAKE: DELOUPE
MODEL:

REGI: 12777169
UNIT/FLEET#: 387
BODY STYLE: Polo Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2D9KD4220H1004016
OWNER/LESSEE NAME: MACRO INDUSTRIES, INC
ADDRESS: PO BOX 6781
Fort St John, British Columbia
V1J4J2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	28	29	16	16	16	16	
2	Clamp	30	Automatic	30	28	16	16	16	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	62	60
2	64	62

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	20	21
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-15 02:57 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, TSCVP at the Commercial Vehicle Safety Enforcement

CVSD014
7/15/2025 2:57:20 PM MST

