

Commercial Vehicle
Inspection ReportDecal Number: GJ60515
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21447422

Inspection Result:

PASS

FACILITY: NORTHERN SPRING, BRAKE & STEERING / S0619
INSPECTOR: HOWE, DAVID EDWARD / 110352
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual

INSP. START: 2025-Aug-01 07:00 AM MST
INSP. COMPLETE: 2025-Aug-01 11:43 AM MST

VEHICLE JUR: British Columbia
PLATE #: G95964

REGI: 03371557
UNIT/FLEET#:

VIN: 3BKDL40X86F987718
OWNER/LESSEE NAME: ESSEX LEASE FINANCIAL CORP(LESSOR), HARDING BRYAN ROBERT(LESSEE)

LICENCED GVW(kg): 63500
VEHICLE YEAR: 2006
MAKE: KENWORTH
MODEL:

BODY STYLE: Truck Tractor
ODOMETER: 840964 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

ADDRESS: PO BOX 1034, PO BOX 1034
Charlie Lake, British Columbia
V0C1H0, Canada

N48-2

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) left front brake pot and air line replaced
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) LEFT FRONT MARKER REPLACED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	inner R	Outer R	Steering
1	Clamp	24	Automatic	34	32	11			12	✓
2	Clamp	30	Automatic	40	40	12	9	9	9	
3	Clamp	30	Automatic	42	42	0	10	9	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	86	Lining (Shoe)	16	12	Drum		
2	43	54	Lining (Shoe)	16	14	Drum		
3	44	50	Lining (Shoe)	16	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: HOWE, DAVID EDWARD

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-01 11:43 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/1/2025 11:43:54 AM MST