



Commercial Vehicle Inspection Report

Decal Number: GJ88196
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21402873

Inspection Result:

PASS

FACILITY: R.JAMES TRUCK AND EQUIPMENT SERVICE / S17382
INSPECTOR: JENSEN, DEANNA LYNN / 202199
WORK ORDER #: GLD012774
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2025-Jun-25 08:43 AM MDT
INSP. COMPLETE: 2025-Jun-25 09:43 AM MDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 1998
MAKE: DECAP
MODEL: CLAM
REGI: 09555227
UNIT/FLEET#: 219
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2D9DS5C35WL017437
OWNER/LESSEE NAME: LTD, GOTTLER BROS. TRUCKING & EXCAVATING
ADDRESS: 1141 11TH AVE N
Golden, British Columbia
V0A1H2, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Repaired (same day) #3L BRAKE POT #3 R & #1R JAM NUT LOOSE
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Not Applicable
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Not Applicable
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31	33	12	16	12	13	
2	Clamp	30	Automatic	34	33	13	13	12	14	
3	Clamp	30	Automatic	33	33	6	9	15	11	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	38	Lining (Shoe)	18	17	Drum		
2	50	37	Lining (Shoe)	15	17	Drum		
3	37	38	Lining (Shoe)	17	17	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: JENSEN, DEANNA LYNN
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-25 09:43 AMMDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.