



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD37589
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21111215

Inspection Result:

PASS

FACILITY: C. KEAY INVESTMENTS LTD. / S14610 INSP. TYPE: Complete INSP. START: 2024-Sep-09 11:30 AM PDT
INSPECTOR: MORTON, CHRISTOPHER / 202091 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2024-Oct-18 10:30 AM PDT
WORK ORDER #: P7387 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 10942706 VIN: 5FTFA5335E1001761
PLATE #: 29079U UNIT/FLEET#: KTSD-301 OWNER/LESSEE NAME: KRISTOFF HOLDINGS LTD., KRISTOFF
LICENCED GVW(kg): 999999 BODY STYLE: Flat Deck Trailer ADDRESS: PO BOX 1106, PO BOX 1106
VEHICLE YEAR: 2014 ODOMETER: Port Edward, British Columbia
MAKE: FELLING HUB ODOMETER: 12660 KM VOV 1G0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACE ROTTEN SHOCKS AND LIMITING STRAPS
Section 3 - Brake System	Repaired (same day) REPLACE LEAKING BRAKE POTS
Section 3A - Air Brakes	Repaired (same day) REPLACE LOW BRAKE SHOES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) REPAIR BURNT OUT LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACE ROTTEN CROSSMEMBERS
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) REPLACE LEAKING WHEEL SEAL
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	51	48	10	11	6	10	
2	Clamp	30	Automatic	51	51	12	11	7	8	
3	Clamp	30	Automatic	51	51	10	10	10	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	40	60
2	40	35
3	45	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	13
Lining (Shoe)	21	14
Lining (Shoe)	16	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: MORTON, CHRISTOPHER Signature:

This Inspection Report was submitted to CVSE on 2024-Oct-18 10:32 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE014

10/18/2024 10:32:18 AM PDT