

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GK48202 2026-Mar-31 21488574 Inspection Result:

PRO-MAK INDUSTRIAL 2019 LTD. / INSP. TYPE: 2025-Sep-08 07:00 AM MST FACILITY: Complete INSP. START: S16430 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Sep-08 08:30 AM MST SHELKIE, DEVON RANDALL / INSPECTOR: 5501 kg or more 300600 INSP. REASON: Semi-annual WORK ORDER #: 4V4NC9KK4FN910508 VEHICLE JUR: British Columbia 14789569 VIN-REGI OWNER/LESSEE NAME: PRO-MAK, INDUSTRIAL LTD PI ATF #: UNIT/FLEET#: LICENCED GVW(kg): 63500 BODY STYLE: ADDRESS; 10238 261 RD Tractor Fort St John, British Columbia ODOMETER: 552090 KM VEHICLE YEAR: 2015 V1J4H9, Canada VOLVO HUB ODOMETER: MAKE: MODEL: BRAKE TYPE: Air **FUEL TYPE:** Vehicle Identification (VIN) Passed Section 1 - Power Train Passed Section 2 - Suspension Passed Section 3 - Brake System Passed Section 3A - Air Brakes Passed Section 3H - Hydraulic Brakes Not Applicable Section 4 - Steering Passed Section 5 - Instruments and Auxiliary Passed Equipment Section 6 - Lamps Passed Section 7 - Electrical System Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Passed

| Air Brake Chamber Type, Size and Push Rod Stroke (mm) | | | | Tire Tread Depth (mm) | | | | | | |
|---|------|------|----------------|-----------------------|-------|----------|---------|---------|---------|----------|
| Axles | Туре | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Disc | N/A | Not Applicable | 0 | 0 | 11 | | | 12 | ~ |
| 2 | Disc | N/A | Not Applicable | 0 | 0 | 21 | 21 | 21 | 21 | |
| 3 | Disc | N/A | Not Applicable | 0 | 0 | 21 | 21 | 21 | 21 | |
| Comment: | | | | | | Comment: | | | | |

| Air Brake Camsha | ft Rotation (degr | ees) | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | | |
|------------------|-------------------|----------|-----------------------|------|-------|--|-------|-------|--|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right | |
| 1 | 0 | 0 | Pad | 13 | 12 | Rotor | 42.20 | 42,20 | |
| 2 | 0 | 0 | Pad | 19 | 20 | Rolar | 42,30 | 42,30 | |
| 3 | 0 | 0 | Pad | 18 | 20 | Rotor | 42,30 | 42,30 | |
| Comment: | | Comment: | | | | Comment: | | | |

Inspection Comments:

Inspector:

Has this Vehicle been road tested? No

Road Test Date: Signature:

Dans

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-08 08:31 AMMST

SHELKIE, DEVON RANDALL

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement CVSED014