



# Commercial Vehicle Inspection Report

Decal Number: PY08918  
Decal Expiry Date: 2025-Nov-30  
Inspection Number: 21347810

Inspection Result:

**PASS**

**FACILITY:** NORTHERN B.C. TRUCKERS' / NS398  
**INSPECTOR:** CHRISTIANSON, LESLIE RYAN / 106407  
**WORK ORDER #:**

**INSPI. TYPE:** Complete  
**INSPI. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSPI. REASON:** Semi-annual

**INSPI. START:** 2025-May-11 12:30 PM MST  
**INSPI. COMPLETE:** 2025-May-11 02:00 PM MST

**VEHICLE JUR:** Alberta  
**PLATE #:** K40862  
**LICENCED GW(kg):** 99999  
**VEHICLE YEAR:** 2012  
**MAKE:** FREIGHTLINER  
**MODEL:** TDM

**REGI:**  
**UNIT/FLEET#:** MP208  
**BODY STYLE:** Truck  
**ODOMETER:** 28422 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:** Diesel

**VIN:** 1FVHCYBSXCDBK1095  
**OWNER/LESSEE NAME:** MACRO INDUSTRIES, INC.  
**ADDRESS:** BOX 931  
ONOWAY, Alberta  
T0E1V0, Canada

Vehicle Identification (VIN) Passed  
Section 1 - Power Train Passed  
Section 2 - Suspension Passed  
Section 3 - Brake System Not Applicable  
Section 3A - Air Brakes Passed  
Section 3H - Hydraulic Brakes Not Applicable  
Section 4 - Steering Passed  
Section 5 - Instruments and Auxiliary Equipment Passed  
Section 6 - Lamps Passed  
Section 7 - Electrical System Passed  
Section 8 - Frame and Body Repaired (same day) NEW WINDOWS  
Section 9A - Tires Passed  
Section 9B - Wheels Passed  
Section 10 - Coupling Devices Passed  
Section 11 - Other Vehicle Components Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	29	30	22			22	✓
2	Clamp	30	Automatic	31	31	24	24	24	24	
3	Clamp	30	Automatic	32	33	24	24	24	24	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	39	39	Lining/Pad	19	19	Rotor/Drum		
2	43	39	Lining (Shoe)	18	19	Drum		
3	36	37	Lining (Shoe)	19	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: CHRISTIANSON, LESLIE RYAN  
Road Test Date:   
Signature: \_\_\_\_\_ Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-12 11:45 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/12/2025 11:46:00 AM MST