



Commercial Vehicle Inspection Report

Decal Number: GH82565
Decal Expiry Date: 2025-Oct-31
Inspection Number: 21322729

Inspection Result:
PASS

FACILITY:	ROJ TRUCK & TRAILER / S6382	INSP. TYPE:	Complete	INSP. START:	2025-Apr-14 12:01 PM PDT
INSPECTOR:	PLUMMER, EDWARD LEVI / 200888	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Apr-24 08:00 AM PDT
WORK ORDER #:	48868	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	03132457	VIN:	1NKDL40X56R987632
PLATE #:	SH6823	UNIT/FLEET#:	HT451	OWNER/LESSEE NAME:	SECURE ENERGY SERVICES INC, SECURE ENERGY SERVICES INC
LICENCED GVW(kg):	57500	BODY STYLE:	Logging Truck	ADDRESS:	13511 VULCAN WAY
VEHICLE YEAR:	2006	ODOMETER:	724090 KM		Richmond, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V6V1K4, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACE DASH VALVE
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) TIE UP HOSES INFRONT OF WINDSHIELD,INSTALL REFLECTORS ON REAR MUDFLAPS
Section 6 - Lamps	Repaired (same day) MOISTURE IN RIGHT LOW BEAM,LEFT BRAKE LIGHT OUT,NO SIGNALS ON HAZARDS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	33	33
2	Clamp	30	Automatic	36	35
3	Clamp	30	Automatic	35	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			9	✓
11	19	19	11	
18	16	17	17	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	25	30
3	30	25

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	18	18
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: PLUMMER, EDWARD LEVI

Road Test Date: See Plummer Road Tester:
Signature:

This Inspection Report was submitted to CVSE on 2025-Apr-24 09:03 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/24/2025 9:03:34 AM PDT