



Commercial Vehicle Inspection Report

Decal Number: GK19097
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21479393

Inspection Result:
PASS

FACILITY: R.JAMES TRUCK AND EQUIPMENT SERVICE / S17362
INSPECTOR: JENSEN, DEANNA LYNN / 202199
WORK ORDER #: GLD013306
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-Aug-30 06:21 AM MDT
INSP. COMPLETE: 2025-Aug-30 07:21 AM MDT
VEHICLE JUR: British Columbia
PLATE #: VR7064
REGI: 12756815
UNIT/FLEET#: 27
VIN: 3HSDTAPT1JN327988
OWNER/LESSEE NAME: DOUBLE T TIMBER, 1629731 ALBERTA LTD.
LICENCED GWV(kg): 63500
VEHICLE YEAR: 2018
MAKE: INTERNATNA
MODEL:
BODY STYLE: Logging Truck
ODOMETER: 412958 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
ADDRESS: 1522 BOONE CRT
Kelowna, British Columbia
V1P1H7, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	YOKE NUT LOOSE AT STEADY BEARING
Section 2 - Suspension	Repaired (same day)	#1 AXLE LS LEAF SPRING BROKEN
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	ALL CLEVIS PINS WORN, #2L & #3L BRAKE POT SPRING, AIR LEAK AT EMERGENCY GLAD HAND
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	B/U LIGHT BROKEN
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	5TH WHEEL PIVOT PINS & BUSHINGS WORN
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	10			10	✓
2	Clamp	30L	Automatic	32	31	14	13	15	16	
3	Clamp	30L	Automatic	31	33	14	15	13	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	66	58
3	60	67

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	14	14
Lining (Shoe)	14	15
Lining (Shoe)	15	14


Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? Yes
Inspector: JENSEN, DEANNA LYNN
Road Test Date: 2025-Aug-30
Signature: 
Road Tester: DEANNA JENSEN

This inspection Report was submitted to CVSE on 2025-Aug-30 09:22 AM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/30/2025 9:22:31 AM MDT