



Commercial Vehicle Inspection Report

A26-1

Decal Number: GH96092
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21336926

Inspection Result:

PASS

FACILITY: PRINCE GEORGE TRUCK AND EQUIPMENT / SS267
INSPECTOR: MACDONALD, DANIEL WILLIAM / 110958
WORK ORDER #: 41875
VEHICLE JUR: British Columbia
PLATE #: VJ9339
LICENCED GVW(kg): 14250
VEHICLE YEAR: 2017
MAKE: KENWORTH
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-May-02 08:00 AM PDT
INSP. COMPLETE: 2025-May-02 03:53 PM PDT
REGI: 14455319
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 1341592 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1XXYD40X6HJ987273
OWNER/LESSEE NAME: BKB CEDAR PRODUCTS LTD, BKB
ADDRESS: PO BOX 314
McBride, British Columbia
V0J2E0, Canada

Vehicle Identification (VIN)	Passed	REPLACED A/C BELT, BAND CLAMP @ CAB REAR TRANS LEAK = CAUTION. REAR BANJO COVER LEAK = CAUTION
Section 1 - Power Train	Repaired (same day)	COMMENTS OF ABOVE
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPLACED L MID CAB MARKER
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	WINDSHIELD REPLACED
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Not Applicable	20	20	10			8	
2	Clamp	30L	Not Applicable	35	35	10	12	13	11	✓
3	Clamp	30L	Not Applicable	40	40	13	16	13	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	48	38
2	73	41
3	36	43

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	18
Lining (Shoe)	13	18
Lining (Shoe)	19	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: MACDONALD, DANIEL WILLIAM
Road Test Date: 05/02/2025
Signature: [Signature]
Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-02 03:53 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The permit information on this form is collected under the authority of section 216 of the Motor Vehicle Act and section 216 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g., regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the CV Manager, NSCVF at the Commercial Vehicle Safety Enforcement.

CVSE/0014

5/2/2025 3:57:19 PM (M)