



BRITISH  
COLUMBIA

## Commercial Vehicle Inspection Report

Decal Number: GK21840  
Decal Expiry Date: 2026-Sep-30  
Inspection Number: 21499215

Inspection Result:

**PASS**

FACILITY: PACIFIC COAST HEAVY TRUCK GROUP / S14140  
INSPECTOR: BLOOMFIELD, JEFFREY WILLIAM GARY / 202754  
WORK ORDER #: 18542  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2025-Sep-16 02:00 PM PDT  
INSP. COMPLETE: 2025-Sep-16 03:00 PM PDT

VEHICLE JUR: British Columbia  
PLATE #: 04041L  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2014  
MAKE: PACESETTER  
MODEL:  
REGI: 10925091  
UNIT/FLEET#: 709N  
BODY STYLE: Lowbed Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
VIN: 2P9LB6539EL096214  
OWNER/LESSEE NAME: TRITON TRANSPORT LTD., TRITON TRANSPORT LTD.  
ADDRESS: 44137 PROGRESS WAY  
Chilliwack, British Columbia  
V2R0W3, Canada  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	70	64
2	Clamp	30	Automatic	70	70
3	Clamp	30	Automatic	64	64

Comment:

### Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	15	15	12	12	
2	16	16	13	11	
3	15	15	14	12	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	70
2	85	20
3	60	85

Comment:

### Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	17	13
2	Lining (Shoe)	12	22
3	Lining (Shoe)	14	12

Comment:


### Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:

Inspector: BLOOMFIELD, JEFFREY WILLIAM GARY Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-16 05:09 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE014

9/16/2025 5:10:15 PM PDT